

Alaska Airport Needs Directory

**Department of Transportation
&
Public Facilities**

As of: August 12, 2013



ADAK ISLAND (ADK)

Runway(s): 05/23 - 7790' x 200'
18/36 - 7605' x 200' **Surface:** Asphalt/Grooved **Lighting:** BCN/HIRL/REIL/PAPI
NAVAIDS: TACAN/DME/NDB

Classification: Community	# Enplanements: 1,897	Borough: Aleutians West
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$5,318.25
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$-
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement:

Airfield Manager: VINCE TUTIAKOFF, 907-842-5511

NEEDS:

Surfaces:

Pavement repair (M&O DM)

Dimensional:

Extend RSA on both runways

RSA expansion

Facilities:

SRE building upgrades (M&O DM)

Equipment:

Dump truck, grader, loader, ARFF vehicle, snow plow equip

4x4 pickup, sweeper, large capacity van

Runway grip tester, new radios (9) for SRE equipment

Comments:

AKHIOK (AKK)

Runway(s): 04/22 - 3120' x 50'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 991

Borough: Kodiak Island

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$6,672.38

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1985

Airfield Manager: ROBERT GREENE, 907-269-0767

NEEDS:

Surfaces:

Runway, taxiway, and apron pavement rehabilitation

Improve runway to accommodate additional use

Dimensional:

Expand the existing runway to 3,120' x 50'

Facilities:

Demolish SRE building & construct new SRE building

Extend 1-bay SREB to include 1 additional bay and heated SREB

Equipment:

Loader & grader

Comments:

Rehabilitate access road

Resurface airport access road

Install lighting (rwy, taxiway, approach lts, navigational)

AKIACHAK (Z13)

Runway(s): 01/19 - 3300' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts/MIRL

NAVAIDS: N/A

Classification: Community

Enplanements: 3,499

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$45,546.66

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2010

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Bulldozer and grader with attachments

Comments:

AKIAK (AKI)

Runway(s): 03/21 - 3196' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 2,180

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$650.00

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$14,786.59

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1998

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

Runway, taxiway, and apron pavement rehabilitation

Dimensional:

Facilities:

Provide a new SREB

Equipment:

Loader and grader with attachments

Comments:

AKUTAN (7AK)

Runway(s): 09/27 - 4500' x 75'

Surface: Asphalt

Lighting: BCN/App_Lts

NAVAIDS: N/A

Classification: Community

Enplanements:

Borough: Aleutians East

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue:

USPS Hub: No

School Facility: Yes

Ops Cost/Yr:

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2012

Airfield Manager: DALE RUCKMAN, 907-581-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Runway broom, grader, loader, 4x4 utility truck, & snow blower

Comments:

ALAKANUK (AUK)

Runway(s): 16/34 - 4000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 3,378

Borough: Wade Hampton

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$61,366.68

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2011

Airfield Manager: HARRY JOHNSON, 907-624-3261

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Loader Wheeled 1.5 CY -- \$350,000

U-Blade Loader 5 CY -- \$350,000

Comments:

ALEKNAGIK (5A8)

Runway(s): 15/33 - 2040' x 80'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 1

Borough: Dillingham

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$19,031.25

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: NORMAN HEYANO, 907-842-5511

NEEDS:

Surfaces:

Dimensional:

Extend current runway to 3,000'

Facilities:

Construct a new SREB

Equipment:

Grader

Comments:

Intent to close or transfer airport to community once aleknagik wood river bridge is constructed connecting Aleknagik to Dillingham

Construct a new float plane dock

Install runway lighting system

ALLAKAKET (6A8)

Runway(s): 05/23 - 4000' x 100'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 2,661

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$2,682.13

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$107,558.98

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2009

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Dimensional:

Facilities:

Allakaket SRE Building Replacement -- \$2,000,000

Equipment:

Snow Wing Grader -- \$350,000

U/V Plow Grader/Loader -- \$350,000

Grader 30,000# -- \$350,000

Dozer Crawler 8-10T -- \$350,000

Comments:

AMBLER (AFM)

Runway(s): 18/36 - 3000' x 60'
09/27 - 2400' x 60' **Surface:** Gravel **Lighting:** BCN/VASI/Rwy_Lts
NAVAIDS: NDB

Classification: Community	# Enplanements: 2,368	Borough: Northwest Arctic
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$2,207.70
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$107,829.68
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 1989

Airfield Manager: CALVIN SCHAEFFER, 907-442-3147

NEEDS:

Surfaces:

Ambler Airport Improvements -- \$15,200,000

Dimensional:

Facilities:

Ambler SRE Building Replacement -- \$2,000,000

Ambler Access Road Improvements -- \$5,500,000

Equipment:

Snowplow Grader -- \$350,000

Snow Wing Grader -- \$350,000

Grader 34,000# -- \$350,000

Dozer Crawler 10-15T -- \$350,000

Comments:

Extend the main and crosswind runway, rehab the operational surfaces and safety area and upgrade the lighting.

ANCHORAGE (ANC) - Ted Stevens Anchorage Intl

Runway(s): 7R/25L - 12400' x 200'
7L/25R - 10600' x 150'
15/33 - 11584' x 150'

Surface: Conc/Asph/Grvd
NAVAIDS: ILS/DME/VOR

Lighting: BCN/App-Rwy_Lts/HIRL/
REIL/PAPI

Classification: International	# Enplanements: 2,354,987	Borough: Anchorage
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$98,640,000.00
USPS Hub: Yes	School Facility: Yes	Ops Cost/Yr: \$111,653,000.00
Part 139 Cert: Yes	On/Off Road: On	Last Major Improvement: 2012

Airfield Manager: JOHN PARROTT, 907-266-2525

NEEDS:

Surfaces:

Pavement maintenance including runway and taxiway rehab

Dimensional:

Additional runway widening and taxiway widening to meet DGVI standards

Facilities:

Equipment:

Regular planned vehicle fleet replacement

Comments:

ANCHORAGE (Z41) - Lake Hood Strip

Runway(s): 14/32 - 2200' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Local

Enplanements: 1,190

Borough: Anchorage

Air Carrier Hub: Yes

Medical Facility: Yes

Annual Revenue:

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$2,000,000.00

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 2006

Airfield Manager: JOHN PARROTT, 907-266-2525

NEEDS:

Surfaces:

Separation of aircraft and auto traffic on Floatplane Drive

Dimensional:

None

Facilities:

Equipment:

Comments:

ANCHORAGE SPB (LHD) - Lake Hood SPB

Runway(s): N/S, E/W, NW/SE - 4540'
Surface: Water
NAVAIDS: N/A

Lighting: BCN

Classification: Local	# Enplanements: 23,497	Borough: Anchorage
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue:
USPS Hub: No	School Facility: Yes	Ops Cost/Yr:
Part 139 Cert: No	On/Off Road: On	Last Major Improvement: 2011

Airfield Manager: JOHN PARROTT, 907-266-2525

NEEDS:

Surfaces:

Additional bank stabilization

Dimensional:

Facilities:

Equipment:

Comments:

ANGOON SPB (AGN)

Runway(s): NW/SE - 10000' x 900'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 1,819

Borough: Hoonah-Angoon

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$650.00

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1987

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

ANIAC (ANI)

Runway(s): 10/28 - 6000' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/App_Lts/HIRL/VASI/Seq
NAVAIDS: ILS/DME/NDB Flshr

Classification: Regional **# Enplanements:** 16,217 **Borough:** Bethel
Air Carrier Hub: Yes **Medical Facility:** Yes **Annual Revenue:** \$79,432.28
USPS Hub: Yes **School Facility:** Yes **Ops Cost/Yr:** \$397,577.46
Part 139 Cert: No **On/Off Road:** Off **Last Major Improvement:** 1995

Airfield Manager: TERRY HOFFMAN, 907-675-4345

NEEDS:

Surfaces:

- Pavement rehab/improvement
- Crack sealing on runway, taxiways, & apron
- Correct pavement markings on runway, taxiways, & apron
- Improve RSA
- Construct helipad, floatplane ramp, and crosswind runway

Dimensional:

- Expand apron

Facilities:

Equipment:

- ARFF vehicle, grader, snow plow, snow blower

Comments:

ANVIK (ANV)

Runway(s): 17/35 - 4000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: NDB

Classification: Community

Enplanements: 911

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$298.84

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$78,531.72

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2004

Airfield Manager: ERIK WEINGARTH, 907-438-2416

NEEDS:

Surfaces:

Anvik Airport Improvements -- \$8,000,000

Dimensional:

Facilities:

Anvik SRE Building Replaceemnt -- \$2,000,000

Equipment:

U-Blade Loader 5CY -- \$350,000

Loader Wheeled 2CY -- \$350,000

Comments:

Resurface runway, apron and taxiway, and upgrade lighting.

ATKA (AKA)

Runway(s): 16/34 - 4500' x 100' **Surface:** Asphalt/Grooved **Lighting:** BCN/Rwy_Lts/REIL
NAVAIDS: N/A

Classification:	Community	# Enplanements:	302	Borough:	Aleutians West
Air Carrier Hub:	No	Medical Facility:	Yes	Annual Revenue:	\$791.27
USPS Hub:	No	School Facility:	Yes	Ops Cost/Yr:	\$7,120.20
Part 139 Cert:	No	On/Off Road:	Off	Last Major Improvement:	2008

Airfield Manager: DALE RUCKMAN, 907-581-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

4X4 Pickup, loader, grader, and sander truck

Comments:

ATMAUTLUAK (4A2)

Runway(s): 15/33 - 3000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 2,376

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$9,855.55

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2002

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

Dimensional:

Facilities:

Construct a 1-bay heated SREB with floor

Equipment:

Grader and loader with attachments

Comments:

BARANOF SPB (BNF) - Warm Spring Bay

Runway(s): E/W - 10000' x 1000'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Wrangell

Air Carrier Hub: No

Medical Facility: No

Annual Revenue:

USPS Hub: No

School Facility: No

Ops Cost/Yr:

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

BARROW (BRW) - Wiley Posts/Will Rogers Memorial

Runway(s): 07/25 - 7100' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN, HIRL, REIL, MALSR
NAVAIDS:
ILS/DME/NDB/VOR

Classification: Regional	# Enplanements: 41,083	Borough: North Slope
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$145,358.34
USPS Hub: Yes	School Facility: Yes	Ops Cost/Yr: \$1,775,412.61
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2010

Airfield Manager: JOHN OLSEN, 907-852-6199

NEEDS:

Surfaces:

- Barrow Apron Expansion -- \$7,000,000
- Barrow Airport Runway Surface Repairs -- \$3,500,000

Dimensional:

Facilities:

- Barrow SREB/ARFF Building Replacement -- \$5,500,000
- Barrow Deicing Chemical Storage Building -- \$3,000,000
- Barrow Airport Security Upgrades -- \$2,500,000
- Barrow Ahkovak Road Improvements (FHWA Funding) -- \$7,700,000

Equipment:

- Utility Wagon Mid 4x4 -- \$350,000
- Broom Runway Towed -- \$350,000

Comments:

Apron Exp-Construct apron and aviation support area expansion. Runway Surface Repairs-Complete surface repairs to address dips on the west end of the runway and longitudinal cracking.

BASIN CREEK

Runway(s): 16/34 - 2000' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Nome

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$19,636.01

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

Acquire 110 acres of land at the Basin Creek Airport.

BEAVER (WBQ)

Runway(s): 05/23 - 3934' x 75'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 1,021

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$1,586.67

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$93,317.41

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1988

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Beaver Airport Improvements ---\$9,000,000

Dimensional:

Facilities:

Beaver SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

Resurface runway and taxiway, expand the apron, apply a dust palliative, and install new lighting.

BETTLES (BTT)

Runway(s): 01/19 - 5190' x 150' **Surface:** Turf/Gravel **Lighting:** BCN/Rwy-App_Lts/VASI
NAVAIDS: VOR/ILS/DME

Classification: Local	# Enplanements: 1,802	Borough: Yukon-Koyukuk
Air Carrier Hub: No	Medical Facility: No	Annual Revenue: \$39,721.65
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$122,300.43
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 1988

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Bettles Airport Rehabilitation -- \$2,000,000

Bettles Airport Paving -- \$4,000,000

Dimensional:

Facilities:

Equipment:

U/V Plow Grader/Loader -- \$350,000

Grader Rural Airport -- \$350,000

Comments:

Resurface the runway, apron and taxiway, upgrade the lighting, remove obstructions and complete grading and drainage improvements.

BETTLES SPB (2A4)

Runway(s): 14/32 - 4100' x 200'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$4,594.65

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2001

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Bettles VOR Lake SPB Improvements -- \$3,000,000

Dimensional:

Facilities:

Equipment:

Comments:

Refurbish the water lane, lease lots and access road to accommodate additional aviation operations, including lease lot development, apron and access road improvements and water lane dredging.

BIG LAKE (BGQ)

Runway(s): 07/25 - 2435' x 70'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: VORTAC

Classification: Local

Enplanements: 10

Borough: Matanuska-Susitna

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$38,473.05

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$34,689.18

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: NEAL HENSLEE, 907-745-2159

NEEDS:

Surfaces:

Runway paving

Construct a GA apron with gravel surface adjacent to airport

Construct taxiways between apron and runway

Dimensional:

Extend taxiway to the east

Expand apron

Facilities:

Construct a 2-bay heated SREB

Equipment:

Loader and 16' snow blade

Comments:

BIRCH CREEK (Z91)

Runway(s): 16/34 - 4000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Local

Enplanements: 772

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$89,004.72

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2003

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Birch Creek Airport Improvements -- \$12,000,000

Dimensional:

Facilities:

Birch Creek SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

Resurface runway and taxiway, expand apron, apply a dust palliative and install new lighting.

BIRCHWOOD (BCV)

Runway(s): 2L/20R - 4010' x 100'
2R/20L - 2200' x 50' **Surface:** Asphalt **Lighting:** BCN/Rwy_Lts/VASI
NAVAIDS: N/A

Classification: Local	# Enplanements:	Borough: Anchorage
Air Carrier Hub: No	Medical Facility: No	Annual Revenue: \$182,217.67
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$53,502.72
Part 139 Cert: No	On/Off Road: On	Last Major Improvement: 2012

Airfield Manager: TOM GRMAN, 907-333-2411

NEEDS:

Surfaces:

- Rehabilitate taxiway, and apron pavement
- Change runway 02/20 desingation marking
- Construct new gravel runway 02S/20S & ultralight runway
- Relocate Taxiway A, construct taxiway D

Dimensional:

- Expand northwest apron

Facilities:

Equipment:

Comments:

BOUNDARY (BYA)

Runway(s): 05/23 - 2325' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$125.88

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1989

Airfield Manager: DENNIS BISHOP, 907-883-5128

NEEDS:

Surfaces:

Boundary Airport Improvements -- \$4,000,000

Dimensional:

Facilities:

Equipment:

Comments:

Resurface runway, apron, and taxiway, apply a dust palliative, and replace airport signage.

BREVIK MISSION (KTS)

Runway(s): 11/29 - 2990' x 100'
04/22 - 2110' x 75'

Surface: Gravel
NAVAIDS: N/A

Lighting: BCN/Rwy_Lts/PAPI

Classification: Community

Enplanements: 2,231

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$60,393.32

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1997

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

Brevik Mission Airport Improvements -- \$10,000,000

Dimensional:

Facilities:

Brevik Mission SRE Building Replacement -- \$2,000,000

Equipment:

U/V Plow Grader/Loader -- \$350,000

Grader 30,000# -- \$350,000

Comments:

Resurface runway, apron, and taxiway, extend Runway 11/29 to 3,400', apply a dust palliative, and upgrade airport lighting.

BUCKLAND (BVK)

Runway(s): 11/29 - 3200' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/VASI

NAVAIDS: N/A

Classification: Community

Enplanements: 3,338

Borough: Northwest Arctic

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$83,568.94

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1996

Airfield Manager: CALVIN SCHAEFFER, 907-442-3147

NEEDS:

Surfaces:

Buckland Airport Improvements -- \$7,500,000

Dimensional:

Facilities:

Buckland SRE Building Replacement -- \$2,000,000

Equipment:

Grader 34,000# -- \$350,000

Dozer Crawler 8-10T-- \$350,000

Comments:

Resurface existing runway and taxiway, extend Runway 11/29 to 3,400', expand the apron, apply a dust palliative, and upgrade airport lighting.

CENTRAL (CEM)

Runway(s): 07/25 - 2782' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 29

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$366.90

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$12,667.05

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1989

Airfield Manager: DANIEL SCHACHER, 907-451-5276

NEEDS:

Surfaces:

Central Airport Improvements -- \$5,500,000

Dimensional:

Facilities:

Central SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

Resurface runway, apron, and taxiway, apply a dust palliative, and upgrade the airport lighting.

CHALKYITSIK (CIK)

Runway(s): 03/21 - 4000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 985

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$52,890.68

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1993

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Chalkyitsik Airport Improvements -- \$10,400,000

Dimensional:

Facilities:

Chalkyitsik SRE Building Replacement -- \$2,000,000

Equipment:

Dozer Crwlr 8-10T-- \$350,000

Comments:

Resurface runway and taxiway, apply a dust palliative, relocate the apron and access road, and rehabilitate the airport lighting system and correct drainage problems at the end of the runway.

CHANDALAR CAMP (5CD) - Chandalar Shelf

Runway(s): 01/19 - 2529' x 70'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$540.00

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 2004

Airfield Manager: JEFF RUSSELL, 907-451-2207

NEEDS:

Surfaces:

Chandalar Camp Runway Rehabilitation -- \$2,500,000

Dimensional:

Facilities:

Equipment:

Comments:

Resurface all operational surfaces, develop lease lots, upgrade signage/markings, and prepare an airport layout plan.

CHANDALAR LAKE (WCR) - Chandalar Lake

Runway(s): 04/22 - 3000' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 25

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$550.00

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$297.75

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1994

Airfield Manager: JEFF RUSSELL, 907-451-2207

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

CHEFORNAK (CFK)

Runway(s): 16/34 - 3230' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 4,087

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$2,482.23

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$19,074.87

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2010

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

Relocate the Chefornak airport 2 miles south

Construct new runway, taxiway, and apron

Dimensional:

Runway length will be no more than 3,300'

Facilities:

Equipment:

Loader & grader with attachments

Comments:

CHENEGA BAY (C05)

Runway(s): 16/34 - 3000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 2,542

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$91,867.74

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2004

Airfield Manager: CARL HIGH, 907-333-2411

NEEDS:

Surfaces:

Resurface runway, taxiways and apron

Dimensional:

Facilities:

Construct a 2-bay SREB

Equipment:

Snow blower, loader, and grader

Comments:

Airport needs fencing, obstacles/penetrations mitigated, erosion study, lease-lot development, Master Plan developed, improved access, and more.

CHEVAK (VAK)

Runway(s): 02/20 - 3200' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 5,578

Borough: Wade Hampton

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$34,360.63

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2005

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

Resurface runway, taxiways and apron

Dimensional:

Facilities:

Construct a 2-bay SREB

Equipment:

Snow blower, loader, and grader

Comments:

Airport needs fencing, obstacles/penetrations mitigated, erosion study, lease-lot development, Master Plan developed, improved access, and more.

CHICKEN (CKX)

Runway(s): 13/31 - 2500' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 8

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$23,634.99

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1987

Airfield Manager: DENNIS BISHOP, 907-883-5128

NEEDS:

Surfaces:

Chicken Airport Improvements -- \$4,500,000

Dimensional:

Facilities:

Chicken SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

Resurface runway, apron, and taxiway, apply a dust palliative, and upgrade the airport lighting.

CHIGNIK (AJC)

Runway(s): 02/20 - 2600' x 60'

Surface: Dirt/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 815

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$1,971.01

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$35,326.39

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1992

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

Resurface runway, taxiway, and apron with 9" of new gravel "Expand SREB to include an additional bay, heat, and insulation

Install concrete pad at SREB entrance" Grader and loader wheel RSA, runway, and taxiway lighting 39

Dimensional:

Facilities:

Chicken SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

Resurface runway, apron, and taxiway, apply a dust palliative, and upgrade the airport lighting.

CHIGNIK LAGOON (KCL)

Runway(s): 04/22 - 1810' x 60'

Surface: Dirt/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 675

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$550.00

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$35,132.81

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

Construct a new 5,000' x 50' runway and associated RSA, apron, taxiway

Resurface existing gravel runway

Dimensional:

Extend runway to 3,200'

Facilities:

Construct a SREB

Equipment:

Snow removal equipment

Comments:

CHIGNIK LAKE (A79)

Runway(s): 08/26 - 2800' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 35

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$1,200.00

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$15,300.92

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1985

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

Resurface runway

Dimensional:

Lengthen/widen runway to community class standards

Expand RSAs and expand apron

Facilities:

Construct a replacement SREB

Equipment:

Grader and snow removal equipment

Comments:

CHISANA (CZN)

Runway(s): 12/30 - 3000' x 50'

Surface: Turf/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 53

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: JOHN HOFFMAN, 907-822-3222

NEEDS:

Surfaces:

Chisana Airport Improvements -- \$3,000,000

Dimensional:

Facilities:

Equipment:

Comments:

Improve airport for all-season operations, including runway surface repairs, brushing, tree clearing and stockpiling surfacing material for future maintenance.

CHISTOCHINA (CZO)

Runway(s): 02/20 - 2060' x 90'

Surface: Turf/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements:

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$379.92

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: JOHN HOFFMAN, 907-822-3222

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

CHITINA (CXC)

Runway(s): 13/31 - 2850' x 75'

Surface: Dirt/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 65

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$2,494.12

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$118.30

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1991

Airfield Manager: JOHN HOFFMAN, 907-822-3222

NEEDS:

Surfaces:

Chitina Airport Paving -- \$900,000

Dimensional:

Facilities:

Chitina SRE Building Upgrade -- \$300,000

Equipment:

Comments:

Pave all operational surfaces and apply airport markings.

CHUATHBALUK (9A3)

Runway(s): 09/27 - 3401' x 60'

Surface: Gravel

Lighting: BCN/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 594

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$25,640.52

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2002

Airfield Manager: TERRY HOFFMAN, 907-675-4345

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Grader and bulldozer

Comments:

CIRCLE (CRC)

Runway(s): 15/33 - 2979' x 60'

Surface: Turf

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 380

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$49,673.00

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1986

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Circle Airport Taxiway and Apron Rehabilitation -- \$1,500,000

Dimensional:

Facilities:

Circle SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

CIRCLE HOT SPRINGS (CHP)

Runway(s): 09/27 - 3650' x 80'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Local

Enplanements: 12

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$21,300.10

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: DANIEL SCHACHER, 907-451-5276

NEEDS:

Surfaces:

Circle Airport Taxiway and Apron Rehabilitation -- \$1,500,000

Dimensional:

Facilities:

Circle SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

CLARKS POINT (CLP)

Runway(s): 18/36 - 3200' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 567

Borough: Dillingham

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$550.00

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$17,174.82

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2004

Airfield Manager: NORMAN HEYANO, 907-842-5511

NEEDS:

Surfaces:

Construct a new runway

Dimensional:

Facilities:

Equipment:

Grader, loader, snow removal equipment

Aviation radio

3 CY LOADER WHEEL

Comments:

CLEAR (Z84)

Runway(s): 01/19 - 3997' x 100'

Surface: Asphalt

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$1,210.00

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$61,525.70

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1993

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

COFFMAN COVE SPB (KCC)

Runway(s): N/S - 5000' x 2000'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 127

Borough: Prince of Wales

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2006

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

COLD BAY (CDB)

Runway(s): 15/33 - 10180' x 150'
08/26 - 6235' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/App_Lts/HIRL/VASI
NAVAIDS: VORTAC/ILS/DME

Classification: Regional	# Enplanements: 9,395	Borough: Aleutians East
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$101,907.57
USPS Hub: Yes	School Facility: Yes	Ops Cost/Yr: \$962,809.07
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2011

Airfield Manager: JEFF DOERNING, 907-532-5000

NEEDS:

Surfaces:

- Rehabilitate north terminal apron, runway 14/32, taxiways
- Construct new pax terminal apron and taxiway
- Construct RSA for runway 8/26

Dimensional:

- Lengthen runway 8/26 by 40'
- RSA expansion to comply with FAA standards (both runways)
- Expand the terminal apron

Facilities:

- 1-bay addition to the existing AARF building
- Standby generator building and additional SRE storage

Equipment:

- ARFF vehicle, dump truck, minivan, loader, snow blower

Comments:

COLDFOOT (CXF)

Runway(s): 01/19 - 4001' x 100'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Local

Enplanements: 340

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$16,019.68

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$12,882.07

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1993

Airfield Manager: JEFF RUSSELL, 907-451-2207

NEEDS:

Surfaces:

Coldfoot Airport Improvements -- \$11,300,000

Dimensional:

Facilities:

Coldfoot SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

Resurface all airport operational surfaces, install permanent erosion control, remove obstructions and install new lighting.

COOPER LANDING (JLA) - Quartz Creek

Runway(s): 04/22 - 2200' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Kenai Peninsula

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$118.32

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: CARL HIGH, 907-262-2199

NEEDS:

Surfaces:

Resurface runway with crushed gravel

Dimensional:

Facilities:

Equipment:

Comments:

Multiple items needed including ROW expansion, property acquisition, lease-lot development, security fencing, geotechnical analysis, and Master Plan update.

COPPER CENTER (Z93) - Copper Center 2

Runway(s): 13/30 - 2200' x 55'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: JOHN HOFFMAN, 907-822-3222

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

CORDOVA (CDV) - Merle K. Smith

Runway(s): 09/27 - 7500' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/App_Lts/HIRL/VASI
NAVAIDS: NDB/ILS/DME

Classification: Regional	# Enplanements: 17,731	Borough: Valdez-Cordova
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$61,063.16
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$806,413.46
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2008

Airfield Manager: ROBERT MATTSON, 907-424-3202

NEEDS:

Surfaces:

- Cordova Airport Apron, Taxiway and GA Improvements Stage 2 -- \$8,500,000
- Cordova Airport RSA Improvements (Drainage) -- \$5,500,000

Dimensional:

Facilities:

- Cordova SREB/ARFF Building Replacement -- \$5,900,000
- Cordova Airport Security Upgrades -- \$2,500,000
- Cordova Eyak Lake SRE Building -- \$2,000,000

Equipment:

Comments:

Construct transient air parking, general aviation parking, access roads, heliport pad, aviation support areas, complete obstruction removal, expand existing apron area, resolve drainage problems and construct partial parallel and connecting taxiways. Rehabilitate the runway safety areas, including grading and drainage improvements, clearing and grubbing.

CORDOVA (CKU) - Cordova Municiple

Runway(s): 06/24 - 1800' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$7,405.03

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$465.37

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: ROBERT MATTSON, 907-424-3202

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Snowplow Rollerover-- \$350,000

Blade Belly-- \$350,000

Truck Plow Airport 4x4-- \$350,000

Utility Wagon Mid 4x4-- \$350,000

Handicap Pass Loader-- \$350,000

Comments:

COUNCIL (K29)

Runway(s): 10/28 - 3000' x 60'

Surface: Gravel

Lighting: BCN/App_Lts

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Nome

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$493.99

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1987

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

CRAIG SPB (CGA)

Runway(s): N/S - 10000' x 2000'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 3,470

Borough: Prince of Wales

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue:

USPS Hub: No

School Facility: Yes

Ops Cost/Yr:

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1995

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

CROOKED CREEK (CJX)

Runway(s): 13/31 - 1997' x 60'

Surface: Earth/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 716

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$1,200.00

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$9,860.17

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1991

Airfield Manager: TERRY HOFFMAN, 907-675-4345

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

CROWN POINT (9Z0) - Lawing

Runway(s): 15/33 - 2200' x 50'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Kenai Peninsula

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$1,645.32

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: CARL HIGH, 907-262-2199

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

DAHL CREEK (DCK)

Runway(s): 08/26 - 4780' x 75'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 174

Borough: Northwest Arctic

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$10,356.19

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$18,112.11

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1986

Airfield Manager: CALVIN SCHAEFFER, 907-442-3147

NEEDS:

Surfaces:

Dahl Creek Airport improvements -- \$8,000,000

Dimensional:

Facilities:

Dahl Creek Airport Lease Lot Development -- \$2,000,000

Equipment:

Comments:

Develop lease lots and expand the apron, including surveying airport lease lots, placing fill material, installing fencing and developing an updated land occupancy drawing.

DEADHORSE (SCC)

Runway(s): 05/23 - 6500' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/App-Rwy/HIRL/VASI/Ctr
NAVAIDS: VOR/ILS/DME Lts

Classification: Regional **# Enplanements:** 37,711 **Borough:** North Slope
Air Carrier Hub: No **Medical Facility:** No **Annual Revenue:** \$1,394,093.78
USPS Hub: No **School Facility:** No **Ops Cost/Yr:** \$1,643,087.66
Part 139 Cert: Yes **On/Off Road:** On **Last Major Improvement:** 2012

Airfield Manager: TIM PARAULT, 907-659-2553

NEEDS:

Surfaces:

Dimensional:

Deadhorse Airport Apron Expansiopn -- \$5,000,000

Facilities:

Deadhorse SREB/ARFF Building Replacement -- \$5,500,000

Deadhorse Airport Security Upgrades -- \$2,500,000

Equipment:

Snowwing Grader-- \$350,000

Truck De-icer 2000 gal-- \$350,000

Grader 30,000#-- \$350,000

Utility Wagon Mid 4x4-- \$350,000

Handicap Pass Loader-- \$350,000

Friction Measure Trailer-- \$350,000

Comments:

Expand the existing apron to accommodate larger aircraft. Deadhorse SREB/ARFF Building Addition-Add two double equipment bays and a sand storage bay to the existing facility.

DEERING (DEE)

Runway(s): 02/20 - 3320' x 75'
11/29 - 2660' x 75'

Surface: Gravel
NAVAIDS: N/A

Lighting: BCN/Rwy_Lts/REIL/PAPI

Classification: Community

Enplanements: 1,488

Borough: Northwest Arctic

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$100,314.98

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2001

Airfield Manager: CALVIN SCHAEFFER, 907-442-3147

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Grader 34,000#-- \$350,000

Comments:

DILLINGHAM (DLG)

Runway(s): 01/19 - 6400' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/App_Lts/VASI/PAPI
NAVAIDS: VOR/ILS/DME

Classification: Regional	# Enplanements: 30,080	Borough: Dillingham
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$102,997.75
USPS Hub: Yes	School Facility: Yes	Ops Cost/Yr: \$1,359,357.51
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2012

Airfield Manager: NORMAN HEYANO, 907-842-5511

NEEDS:

Surfaces:

- Reconstruct and pave public parking area
- Rehabilitate GA/commercial apron and taxiway
- Rehabilitate taxiway and apron
- Pave vehicle parking area
- Construct a parallel taxiway, RSA, and 2000'crosswind runway

Dimensional:

- Expand RSA, main terminal apron, and vehicle parking

Facilities:

- Install new public toilets
- Expand the existing sand storage building

Equipment:

- ARFF vehicle, loader, minivan, SRE truck, bulldozer, snow removal equipment
- 5,000 gal water tanker and 4,000 gal deicer truck

Comments:

- Install fencing & drainage, remove obstructions at west end of runway, extend lease-lot access road, and complete airport planning study.

EAGLE (EAA)

Runway(s): 06/24 - 3600' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/VASI

NAVAIDS: N/A

Classification: Community

Enplanements: 638

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$4,919.85

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$55,559.44

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1984

Airfield Manager: DENNIS BISHOP, 907-883-5128

NEEDS:

Surfaces:

Eagle Airport improvements -- \$2,000,000

Dimensional:

Facilities:

Equipment:

Comments:

Resurface runway and taxiway, relocate the apron and access road to meet standards, improve sub-grade and drainage, and install new lighting.

EEK (EEK)

Runway(s): 17/35 - 3242' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 3,618

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$23,664.65

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2002

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

- Construct a 2,400' x 60' gravel crosswind runway w/ RSA
- Construct a 100,000 sqft apron and aviation support area
- Construct a segmented circle

Dimensional:

Facilities:

- Construct a new SREB

Equipment:

- Grader and loader

Comments:

EKWOK (KEK)

Runway(s): 02/20 - 3300' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 377

Borough: Dillingham

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$100.00

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$43,391.11

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2008

Airfield Manager: NORMAN HEYANO, 907-842-5511

NEEDS:

Surfaces:

Dimensional:

Expand gravel runway to 3,300' x 75'

Shift runway NE by 350' & rotate 6 degrees counterclockwise

Expand RSA's

Facilities:

Equipment:

Grader, wheel, loader

Comments:

Multiple items needed including ROW expansion, property acquisition, lease-lot development, security fencing, geotechnical analysis, and Master Plan update.

ELFIN COVE SPB (ELV)

Runway(s): NW/SE - 10000' x 1500' **Surface:** Water **Lighting:** N/A
NAVAIDS: N/A

Classification: Local	# Enplanements: 358	Borough: Hoonah-Angoon
Air Carrier Hub: No	Medical Facility: No	Annual Revenue:
USPS Hub: No	School Facility: No	Ops Cost/Yr:
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement:

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

FY'16 Replace Seaplane Float -- \$500,000

Dimensional:

Facilities:

Equipment:

Comments:

ELIM (ELI)

Runway(s): 01/19 - 3401' x 60'	Surface: Gravel	Lighting: BCN/Rwy_Lts
	NAVAIDS: N/A	
Classification: Community	# Enplanements: 2,570	Borough: Nome
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$-
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$104,417.34
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 2008

Airfield Manager: HARRY JOHNSON, 907-624-3261

NEEDS:

Surfaces:

Elim Airport Improvements -- \$8,000,000

Dimensional:

Facilities:

Elim SRE Building Replacement -- \$2,000,000,
Elim Airport Access Road Realignment -- \$7,000,000

Equipment:

Dozer Crwlr 8-10T-- \$350,000

Comments:

Resurface runway, apron and taxiway, improve drainage, and install new lighting.

EMMONAK (ENM)

Runway(s): 16/34 - 4601' x 100'

Surface: Gravel

Lighting: BCN/Rwy_Lts/VASI/REIL

NAVAIDS: VOR/DME

Classification: Regional

Enplanements: 9,174

Borough: Wade Hampton

Air Carrier Hub: Yes

Medical Facility: Yes

Annual Revenue: \$5,326.73

USPS Hub: Yes

School Facility: Yes

Ops Cost/Yr: \$146,145.93

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2009

Airfield Manager: HARRY JOHNSON, 907-624-3251

NEEDS:

Surfaces:

Dimensional:

Emmonak Airport Runway Extension -- \$18,400,000

Emmonak Airport RSA Improvements -- \$1,000,000

Facilities:

Emmonak Airport SRE Building -- \$2,100,000

Equipment:

U-Blade Loader 5CY -- \$350,000

Dozer Crawler 8-10T -- \$350,000

Loader Wheeled 1.5 CY -- \$350,000

Comments:

Extend the runway to 6,000' and the existing safety area to 7,200' x 300', acquire land for extension, and install new lighting.

EXCURSION INLET SPB (EXI)

Runway(s): NW/SE - 10000' x 1000' **Surface:** Water **Lighting:** N/A
NAVAIDS: N/A

Classification: Local	# Enplanements: 75	Borough: Haines
Air Carrier Hub: No	Medical Facility: No	Annual Revenue:
USPS Hub: No	School Facility: No	Ops Cost/Yr:
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement:

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

FY'20 Replace Seaplane Float -- \$1,250,000

Dimensional:

Facilities:

Equipment:

Comments:

FAIRBANKS (FAI) - Fairbanks Intl

Runway(s): 2L/20R - 11800' x 150'
2R/20L - 6501' x 100'

Surface: Asphalt/Grooved

Lighting: BCN/App-Rwy_Lts/HIRL/
REIL/PAPI

NAVAIDS: VORTAC/ILS/DME

Classification: International

Enplanements: 438,188

Borough: Fairbanks/North Star

Air Carrier Hub: Yes

Medical Facility: Yes

Annual Revenue: \$8,124,000.00

USPS Hub: Yes

School Facility: Yes

Ops Cost/Yr: \$27,592,000.00

Part 139 Cert: Yes

On/Off Road: On

Last Major Improvement: 2012

Airfield Manager: JESSE VANDERZANDEN, 907-474-2500

NEEDS:

Surfaces:

Tie down apron areas, various roadways

Dimensional:

Facilities:

ARFF Facility remodel 9/13 thru 12/14

Equipment:

Regular planned vehicle fleet replacement

Comments:

FAIRBANKS SPB (FAI)

Runway(s): 02/20 - 5400' x 100'

Surface: Water

Lighting: BCN

NAVAIDS: N/A

Classification: International

Enplanements:

Borough: Fairbanks/North Star

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue:

USPS Hub: No

School Facility: Yes

Ops Cost/Yr:

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: JESSE VANDERZANDEN, 907-474-2500

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

FALSE PASS (KFP)

Runway(s): 04/32 - 2150' x 60'

Surface: Gravel

Lighting: REIL

NAVAIDS: N/A

Classification: Community

Enplanements: 409

Borough: Aleutians East

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$795.00

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$27,021.89

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1988

Airfield Manager: JEFF DOERNING, 907-532-5000

NEEDS:

Surfaces:

Airport reconstruction

Dimensional:

Extend airport to 2,700' with adequate safety areas

Extend the runway length to 3,100'

Facilities:

Extend 2-bay SREB

Construction of 2-bay heated SREB

Equipment:

SNOWPLOW GRADER

Replace Champion Grader

Champion grader

Comments:

FLAT (FLT)

Runway(s): 08/26 - 4045' x 90'

Surface: Turf/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 10

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: DOUG LYMAN, 907-745-2159

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

FORT YUKON (FYU)

Runway(s): 04/22 - 5000' x 100'

Surface: Gravel

Lighting: BCN/App-Rwy_Lts/VASI

NAVAIDS: VORTAC/NDB

Classification: Regional

Enplanements: 9,444

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$27,095.86

USPS Hub: Yes

School Facility: Yes

Ops Cost/Yr: \$52,303.34

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2009

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

FUNTER BAY SPB (FNR)

Runway(s): NE/SW - 10500' x 500'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 15

Borough: Hoonah-Angoon

Air Carrier Hub: No

Medical Facility: No

Annual Revenue:

USPS Hub: No

School Facility: No

Ops Cost/Yr:

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

FY'23 Replace Seaplane Float -- \$500,000

Dimensional:

Facilities:

Equipment:

Comments:

GALBRAITH LAKE (GBH)

Runway(s): 13/31 - 5182' x 150'

Surface: Gravel

Lighting: BCN/App-Rwy_Lts/PAPI

NAVAIDS: NDB

Classification: Local

Enplanements: 719

Borough: North Slope

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$4,039.36

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$-

Part 139 Cert: Yes

On/Off Road: Off

Last Major Improvement:

Airfield Manager: JEFF RUSSELL, 907-451-2207

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

Extend the land lease with the BLM.

GALENA (GAL) - Edward G. Pitka Sr.

Runway(s): 07/25 - 7249' x 150' **Surface:** Concrete/Asphalt **Lighting:** BCN/HIRL/VASI/REIL
NAVAIDS: VOR/DME

Classification: Regional	# Enplanements: 10,862	Borough: Yukon-Koyukuk
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$56,541.03
USPS Hub: Yes	School Facility: Yes	Ops Cost/Yr: \$586,004.59
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 2009

Airfield Manager: MARVIN THURMOND, 907-656-1236

NEEDS:

Surfaces:

Galena Airport Improvements -- \$16,300,000

Dimensional:

Facilities:

Galena Airport Lighting Replacement -- \$2200,000

Equipment:

Comments:

Resurface Runway 7/25 and Taxiway "B" at the Galena Airport, repair the general aviation (GA) apron.

GAMBELL (GAM)

Runway(s): 16/34 - 4499' x 96' **Surface:** Concrete/Asphalt **Lighting:** BCN/App-Rwy_Lts/VASI/REIL
NAVAIDS: NDB/DME

Classification: Community	# Enplanements: 3,429	Borough: Nome
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$220.00
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$124,288.10
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 1997

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Grader 34,000# -- \$350,000

U/V Plow Grader/Loader -- \$350,000

Comments:

GIRDWOOD (AQY)

Runway(s): 02/20 - 2088' x 73'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Anchorage

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$26,932.69

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$9,838.42

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 2002

Airfield Manager: LARRY BUSHNELL, 907-783-2232

NEEDS:

Surfaces:

Relocate both thresholds

Provide 3,500 linear feet of erosion protection for runway embankment

Dimensional:

Extend parallel taxiway to the north

Expand the southern RSA 116' southward

Extend the RSA embankment 116' south

Expand apron and runway

Facilities:

Equipment:

Comments:

GLENALLEN/GULKANA (GKN)

Runway(s): 15/33 - 5001' x 100' **Surface:** Asphalt **Lighting:** BCN/Rwy_Lts/VASI
NAVAIDS: N/A

Classification: Community	# Enplanements: 136	Borough: Valdez-Cordova
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$18,204.24
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$91,110.51
Part 139 Cert: No	On/Off Road: On	Last Major Improvement:

Airfield Manager: JOHN HOFFMAN, 907-822-3222

NEEDS:

Surfaces:

Gulkana Airport Apron and Taxiway Repaving -- \$3,000,000

Dimensional:

Facilities:

Equipment:

Comments:

Reconstruct the pavement on the apron and taxiway, remove obstacles and install airport markings/signage.

GOLD KING CREEK (AK7)

Runway(s): 09/27 - 2500'

Surface: Dirt/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Fairbanks/North Star

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Gold King Airport Improvements -- \$2,000,000

Dimensional:

Facilities:

Equipment:

Comments:

Improve airport for all-season operations, including runway surface repairs, brushing, tree clearing and stockpiling surfacing material for future maintenance.

GOLOVIN (GLV)

Runway(s): 02/20 - 4000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 1,916

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$88,963.74

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1992

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

Golovin Airport Runway and Apron Improvements -- \$14,300,000

Dimensional:

Facilities:

Equipment:

Grader 34,000# -- \$350,000

Comments:

Resurface and rehabilitate the runway, construct a new taxiway, apron and access road, and replace the existing airport lighting

GOODNEWS (GNU)

Runway(s): 06/24 - 3300' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 1,599

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$29,614.56

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2008

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

Airport reconstruction

Dimensional:

Facilities:

Equipment:

Grader, loader, snow plow

Comments:

GOOSE BAY (Z40)

Runway(s): 08/26 - 3000' x 75'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Matanuska-Susitna

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$5,495.50

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1987

Airfield Manager: NEAL HENSLEE, 907-745-2159

NEEDS:

Surfaces:

Runway resurfacing

Dimensional:

Facilities:

Equipment:

Comments:

GRAYLING (KGX)

Runway(s): 17/35 - 4000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 1,025

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$57,753.99

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2008

Airfield Manager: ERIK WEINGARTH, 907-438-2416

NEEDS:

Surfaces:

Grayling Airport Improvements -- \$7,000,000

Dimensional:

Facilities:

Grayling SRE Building Replacement -- \$2,000,000

Equipment:

U/V Plow Grader/Loader -- \$350,000, Grader 30,000# -- \$350,000, Dozer Crawler 8-10T -- \$350,000

Comments:

GUSTAVUS (GST)

Runway(s): 11/29 - 6721' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/Rwy_Lts/VASI/REIL
NAVAIDS: NDB

Classification: Regional	# Enplanements: 11,537	Borough: Hoonah-Angoon
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$46,925.72
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$176,017.80
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2011

Airfield Manager: MIKE PEDERSEN, 907-789-1786

NEEDS:

Surfaces:

FY'16 RWY/TWY/Apron Rehab -- \$12,000,000

Dimensional:

Facilities:

FY'16 Sand and Chem Building -- \$1,700,000

FY'16 ARFF/SRE Building -- \$1,200,000

Equipment:

FY'19 ARFF Truck -- \$1,000,000

Comments:

HAINES (HNS)

Runway(s): 08/26 - 4000' x 100'

Surface: Asphalt

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: NDB

Classification: Community

Enplanements: 8,618

Borough: Haines

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$16,838.61

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$22,914.60

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1990

Airfield Manager: MATT BORON, 907-766-2340

NEEDS:

Surfaces:

FY'14 TWY & Apron Drainage improvement, rehab -- \$10,000,000

FY'16 RWY Rehab -- \$6,000,000

Dimensional:

FY'19 Apron Expansion -- \$1,300,000

Facilities:

FY'16 Sand and Chem/SRE Building -- \$2,000,000

Equipment:

Comments:

HEALY (HRR)

Runway(s): 15/33 - 2912' x 60'

Surface: Asphalt

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 5

Borough: Denali

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$6,293.50

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$23,521.53

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1995

Airfield Manager: TOM WILLIAMS, 907-451-5280

NEEDS:

Surfaces:

Healy River Airport Resurfacing -- \$4,500,000

Dimensional:

Facilities:

Healy River Airport Lighting Replacement -- \$1,700,000

Equipment:

Comments:

Resurface all operational surfaces. Healy River Airport Lighting Rep-Replace the airport lighting system.

HOLLIS - Hollis SPB

Runway(s):	Surface: Water NAVAIDS: N/A	Lighting: N/A
Classification:	# Enplanements:	Borough: Prince of Wales
Air Carrier Hub:	Medical Facility:	Annual Revenue: \$-
USPS Hub:	School Facility:	Ops Cost/Yr: \$-
Part 139 Cert:	On/Off Road: Off	Last Major Improvement:

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

HOLLIS SPB (HYL) - Clark Bay SPB

Runway(s): E/W - 10000' x 500'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 1,650

Borough: Prince of Wales

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$550.00

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2006

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

HOLY CROSS (HCA)

Runway(s): 01/19 - 4000' x 100'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 1,223

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$100.00

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$55,691.68

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2001

Airfield Manager: ERIK WEINGARTH, 907-438-2416

NEEDS:

Surfaces:

Holy Cross Airport Improvements -- \$7,500,000

Dimensional:

Facilities:

Holy Cross SRE Building Replacement -- \$2,000,000

Equipment:

U-Blade Loader 5CY -- \$350,000

Loader Wheeled 1.5CY -- \$350,000

Comments:

Raise the grade, clear obstructions, resurface all operational surfaces and install new airport lighting.

HOMER (HOM)

Runway(s): 03/21 - 6701' x 150' **Surface:** Asphalt **Lighting:** BCN/App_Lts/HIRL/VASI
NAVAIDS: VOR/ILS/DME

Classification: Regional	# Enplanements: 35,863	Borough: Kenai Peninsula
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$157,595.97
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$668,693.01
Part 139 Cert: Yes	On/Off Road: On	Last Major Improvement: 2011

Airfield Manager: KEVIN JONES, 907-235-8872

NEEDS:

Surfaces:

- Rehabilitate runway, taxiway, and apron
- Address Part 139 RSA issues along runway 03/21
- Construct a full-length parallel taxiway on north side of runway 3/21
- Construct multiple connective taxiways, heliport, and access ramp
- 30-space vehicle parking lot

Dimensional:

- Extend taxiways, south apron, and GA apron toward Lampert Lake

Facilities:

- Lease lot acquisition for ARFF/SREB
- Demo existing SREB and construct new 5-bay facility w/ FSS
- Build a new multi-bay ARFF building
- Chemical and deicing material storage facility
- Construct a rescue boat house and lake side floats

Equipment:

- ARFF vehicle, dump truck, pax loader, minivan, grader
- 4,000 gal deicer truck

Comments:

HOMER SPB (5BL) - Homer-Beluga Lake

Runway(s): NE/SW - 3000' x 600'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Kenai Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue:

USPS Hub: No

School Facility: Yes

Ops Cost/Yr:

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: KEVIN JONES, 907-225-8872

NEEDS:

Surfaces:

Improvements

Dimensional:

Facilities:

Equipment:

Comments:

HOONAH (HNN)

Runway(s): 06/24 - 2997' x 75'

Surface: Asphalt

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 10,815

Borough: Hoonah-Angoon

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$7,836.04

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$63,092.54

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2012

Airfield Manager: KEN MESERVE, 907-945-3426

NEEDS:

Surfaces:

FY'18 Apron/TWY Rehab -- \$3,000,000

Dimensional:

FY'19 Obstruction Removal -- \$500,000

Facilities:

Equipment:

Comments:

HOONAH SPB (OOH)

Runway(s): E/W - 9000' x 5000'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Hoonah-Angoon

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue:

USPS Hub: No

School Facility: Yes

Ops Cost/Yr:

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: KEN MESERVE, 907-945-3426

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

HOOPER BAY (HPB)

Runway(s): 13/31 - 3300' x 75' **Surface:** Asphalt/Grooved **Lighting:** BCN/App-Rwy_Lts/VASI
NAVAIDS: VOR/DME

Classification: Community	# Enplanements: 6,039	Borough: Wade Hampton
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$890.00
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$66,707.30
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 2005

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

- Rehabilitate runway pavement
- Relocate apron

Dimensional:

- Expand apron and runway to 4,500'

Facilities:

- Construct a new SREB

Equipment:

- Snow blower, loader, grader

Comments:

- Needs access road, lighting and land acquisition

HOPE (5HO)

Runway(s): 16/34 - 2000' x 90'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements:

Borough: Kenai Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$2,047.56

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$2,530.62

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: LARRY ANDERSON, 907-269-5672

NEEDS:

Surfaces:

Construct a GA apron

Construct a taxiway

Reconstruct the runway to A2 standards

Dimensional:

Facilities:

Equipment:

Comments:

Resurface access road, install lighting, and electrical power to M&O building

HUGHES (HUS)

Runway(s): 17/35 - 3380' x 100'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 1,182

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$75,626.63

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1990

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Hughes Airport Improvements -- \$3,800,000

Dimensional:

Facilities:

Hughes SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

Raise the grade of the airport, relocate the apron, and apply dust palliative on operational surfaces.

HUSLIA (HLA)

Runway(s): 03/21 - 4000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: VOR/DME

Classification: Community

Enplanements: 3,232

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$100.00

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$75,483.59

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2010

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Dimensional:

Facilities:

Huslia SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

HYDABURG SPB (HYG)

Runway(s): E/W - 5000' x 2000'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 74

Borough: Prince of Wales

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1994

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

HYDER SPB (4Z7)

Runway(s): N/S - 10000' x 1000'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 92

Borough: Prince of Wales

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 2002

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

IGIUGIG (IGG)

Runway(s): 05/23 - 3000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 944

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$2,225.00

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$29,260.01

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1993

Airfield Manager: CLINT ANELON, 907-571-7171

NEEDS:

Surfaces:

Resurface runway, approaches, and apron resurface

Dimensional:

Extend runway 05/23 to 4,200'

Expand apron by 300'

Facilities:

Construct heated 1-bay SREB

Equipment:

Grader, loader, snow removal equipment

Comments:

Relocate utility line extension and install lighting (MIRL)

ILIAMNA (ILI)

Runway(s): 07/25 - 5086' x 100'
17/35 - 4800' x 100' **Surface:** Asphalt/Grooved **Lighting:** BCN/Rwy_Lts/REIL/PAPI
NAVAIDS: NDB/DME

Classification: Regional	# Enplanements: 6,318	Borough: Lake & Peninsula
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$79,045.76
USPS Hub: Yes	School Facility: Yes	Ops Cost/Yr: \$765,156.53
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 2002

Airfield Manager: CLINT ANELON, 907-571-7171

NEEDS:

Surfaces:

- Pavement reseal on runways, taxiways, and apron
- Construct new waterlane, light jet apron, and helicopter staging area

Dimensional:

- Lengthen the crosswind runway

Facilities:

- Expand the existing 5 bay M&O building
- Demolish/relocate the hotel on airport property

Equipment:

- ARFF vehicle, pickup truck, minivan, snow blower, grader
- Fire truck, compactor, Friction measuring trailer

Comments:

ILIAMNA (ILI) - Iliamna Pike Lake

Runway(s): N/S - 2892' x 400'
E/W - 2998' x 400'

Surface: Water
NAVAIDS: N/A

Lighting: N/A

Classification: Regional

Enplanements: 7,396

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue:

USPS Hub: No

School Facility: Yes

Ops Cost/Yr:

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: CLINT ANELON, 907-571-7171

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

Runway cannot be lengthened and is in good condition.

Lighting is not necessary as no planes fly at night due to terrain penetrations.

Culvert replacement

Needs runway, taxiway, and apron lighting

KAKE (KAE)

Runway(s): 11/29 - 4000' x 100'	Surface: Asphalt	Lighting: Rwy_Lts/REIL/PAPI
	NAVAIDS: NDB	
Classification: Community	# Enplanements: 1,469	Borough: Wrangell
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$550.00
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$58,466.07
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 1989

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

FY'16 -- RWY Rehab -- \$5,000,000

Dimensional:

FY'22 Obstruction Removal and RWY Extension -- \$12,000,000

FY'23 Apron Expansion -- \$2,000,000

Facilities:

FY'18 SRE Building & Parking Lot -- \$2,500,000

Equipment:

Comments:

KALSKAG (KLG)

Runway(s): 06/24 - 3172' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 3,538

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$3,584.99

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$34,723.91

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1999

Airfield Manager: TERRY HOFFMAN, 907-675-4345

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Grader

Comments:

Runway was lengthened from 1,600' to 2,200' x 60'. No RSA at this airport. Airport cannot be improved to FAA standards without severe impacts to the community. Needs 10' of gravel access road.

KALTAG (KAL)

Runway(s): 03/21 - 3986' x 100'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 1,969

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$1,369.74

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$81,003.86

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1991

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Kaltag Airport Improvements -- \$5,000,000

Dimensional:

Facilities:

Kaltag SRE Building Replacement -- \$2,000,000

Equipment:

Dozer Crwlr 8-10T -- \$350,000

Comments:

Rehabilitate all operational surfaces, replace the lighting system, and apply a dust palliative.

KANTISHNA (5Z5)

Runway(s): 10/28 - 1950' x 45'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: TOM WILLIAMS, 907-451-5280

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

KARLUK (KYK)

Runway(s): 10/28 - 2000' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 442

Borough: Kodiak Island

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$11,716.40

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: ROBERT GREENE, 907-487-4952

NEEDS:

Surfaces:

Airport surface rehabilitation

Dimensional:

Apron extension by 200'

Extend runway to 3,000'

Facilities:

Construct new maintenance building

Equipment:

30,000 LB GRADER

Comments:

Needs runway lighting, MIRLS. Improving airport to FAA standards will be very expensive for the low population of the community.

Lighting is not recommended due to terrain penetrations.

KASAAN SPB (KXA)

Runway(s): N/S - 2000' x 2000'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 97

Borough: Prince of Wales

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1989

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

KASIGLUK (Z09)

Runway(s): 17/35 - 3000' x 60'

Surface: Gravel

Lighting: Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 4,674

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$36,773.98

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1997

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

Dimensional:

Facilities:

Construct a 1-bay heated SREB with floor

Equipment:

Loader and grader

Comments:

KASILOF (5KS)

Runway(s): 01/19 - 2165' x 40'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Kenai Peninsula

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$306.54

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: CARL HIGH, 907-262-2199

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

KETCHIKAN (KTN) - Ketchikan Intl

Runway(s): 11/29 - 7500' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/App_Lts/HIRL/PAPI
NAVAIDS: ILS/DME/NDB

Classification: Regional	# Enplanements: 102,086	Borough: Ketchikan Gateway
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$-
USPS Hub: Yes	School Facility: Yes	Ops Cost/Yr: \$315,194.98
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2007

Airfield Manager: MIKE CARNEY, 907-225-6800

NEEDS:

Surfaces:

FY'14 TWY/Apron Rehab -- \$10,000,000

Dimensional:

FY'16 Construct Seaplane Haulout Ramp -- \$600,000

Facilities:

FY'15 Expand/Rehab ARFF Building -- \$1,000,000

FY'23 Second Airport Ferry Berth -- \$2,000,000

Equipment:

FY'15 30' Trap Plow -- \$35,000

FY'16 Self-Propelled Runway Broom -- \$550,000

FY'17 Deicing Truck -- \$350,000

Comments:

KETCHIKAN AIRPORT SPB (KTN)

Runway(s): NW/SE - 9500' x 1500'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Regional

Enplanements:

Borough: Ketchikan Gateway

Air Carrier Hub: Yes

Medical Facility: Yes

Annual Revenue:

USPS Hub: No

School Facility: Yes

Ops Cost/Yr:

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: MIKE CARNEY, 907-225-6800

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

KETCHIKAN SPB (9C0) - Peninsula Point Pullout

Runway(s): NE/SW - 9000' x 2000' **Surface:** Water **Lighting:** N/A
NAVAIDS: N/A

Classification: Local	# Enplanements:	Borough: Ketchikan Gateway
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$60,530.34
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$-
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement:

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

KIANA (IAN) - Bob Baker Memorial

Runway(s): 06/24 - 3400' x 100'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 3,267

Borough: Northwest Arctic

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$2,402.91

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$99,922.75

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1996

Airfield Manager: CALVIN SCHAEFFER, 907-442-3147

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

Extend the runway, rehabilitate the operational surfaces, expand the apron, improve the aircraft parking setback, acquire land, replace the lighting system, and apply a dust palliative.

KING COVE (KVC)

Runway(s): 07/25 - 3500' x 100'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 3,040

Borough: Aleutians East

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$3,392.21

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$32,858.58

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2005

Airfield Manager: JEFF DOERNING, 907-532-5000

NEEDS:

Surfaces:

Repave runway, taxiway, and apron

Dimensional:

Expand RSA to 4,200' x 150'

Expand runway to 3,600' x 100'

Widen taxiway to 79'

Facilities:

Construct 3 SREBs

Construct 8' x 10' heated passenger shelter

Equipment:

Loader and grader

Comments:

KING SALMON (AKN)

Runway(s): 12/30 - 8901' x 150' **Surface:** Asphalt **Lighting:** BCN/App_Lts/REIL/PAPI
NAVAIDS: ILS/DME/VORTAC

Classification: Regional	# Enplanements: 40,345	Borough: Bristol Bay
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$135,207.84
USPS Hub: Yes	School Facility: Yes	Ops Cost/Yr: \$1,124,872.91
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2011

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

Resurface runway, taxiways, and apron

Dimensional:

Facilities:

Install new public toilets and transit apron shelter
Construct a new sand storage building

Equipment:

Loader, grader, ARFF truck, bulldozer
Minivan, friction measuring trailer

Comments:

Rehabilitate access road

KING SALMON SPB (AKN)

Runway(s): NW/SE - 4000' x 500'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Regional

Enplanements:

Borough: Bristol Bay

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue:

USPS Hub: No

School Facility: Yes

Ops Cost/Yr:

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

Construct a safety area on runway 11/29

Pave vehicle parking

Replace blast pad and segmented circle

Dimensional:

Expand vehicle parking and apron

Facilities:

Equipment:

Comments:

KIPNUK (IIK)

Runway(s): 17/35 - 3200' x 60'

Surface: Gravel

Lighting: Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 5,780

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$705.00

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$25,245.21

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2010

Airfield Manager: DAVE CUMMINGS, 907-543-2945

NEEDS:

Surfaces:

- Repair the embankment
- Construct new 3,200' x 75' runway (B-II standards)
- Construct new taxiway, apron, and apron access
- Construct a new 2,400' x 60' gravel crosswind runway
- Construct a 2,980' x 120' RSA
- Construct runway embankments and segmented circle

Dimensional:

- Extend the embankment
- Increase the RSA to 3,800' x 150'

Facilities:

- Construct two SREBs and a temporary facility

Equipment:

- 30,000 LB GRADER

Comments:

KIVALINA (KVL)

Runway(s): 12/30 - 3000' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 3,274

Borough: Northwest Arctic

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$75,184.83

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2001

Airfield Manager: CALVIN SCHAEFFER, 907-442-3147

NEEDS:

Surfaces:

Kivalina Airport Erosion Control -- \$7,200,000

Dimensional:

Facilities:

Kivalina SRE Building Replacement -- \$2,000,000

Equipment:

U-Blade Loader 10CY -- \$350,000

Loader Wheeled 1.5CY -- \$350,000

Comments:

Permanently repair erosion damage and install permanent beach erosion control.

KLAWOCK (AKW)

Runway(s): 02/20 - 5000' x 100'

Surface: Asphalt

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: NDB

Classification: Community

Enplanements: 16

Borough: Prince of Wales

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$20,771.26

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$70,106.00

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1992

Airfield Manager: TIM LACOUR, 907-755-2229

NEEDS:

Surfaces:

FY'16 Apron Expansion and Rehab -- \$5,000,000

Dimensional:

FY'18 New TWY to Lease Lots -- \$2,750,000

FY'20 Obstruction Removal -- \$5,000,000

Facilities:

FY'23 Airport Seaplane Float and Haul Out -- \$3,500,000

Equipment:

Comments:

KOBUK (OBU)

Runway(s): 09/27 - 4020' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 1,417

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$79,278.90

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2003

Airfield Manager: CALVIN SCHAEFFER, 907-442-3147

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Dozer Crawler 8-10T -- \$350,000

Grader Rural Arpt -- \$350,000

Comments:

KODIAK (ADQ) - Kodiak Benny Benson

Runway(s): 07/25 - 7550' x 150'
11/29 - 5400' x 150'
18/36 - 5010' x 150'

Surface: Asphalt/Grooved
NAVAIDS: VOR/ILS/DME

Lighting: BCN/HIRL/VASI/REIL

Classification: Regional	# Enplanements: 81,149	Borough: Kodiak Island
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$157,489.52
USPS Hub: Yes	School Facility: Yes	Ops Cost/Yr: \$1,463,807.17
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2011

Airfield Manager: ROB GREENE, 907-487-4952

NEEDS:

Surfaces:

Rehabilitate runway 18/36 and 7/25 and associated taxiways & parking

Dimensional:

Extend RSAs on runways 18/36 and 7/25
Expand RSA - EIS

Facilities:

Construct replacement regulator building

Equipment:

Snowplow, grader, ARFF vehicle, bulldozer
minivan, loader wheel, snow blower

Comments:

Install runway lighting

KOKHANOK (9K2)

Runway(s): 06/24 - 3300' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 1,277

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$1,200.00

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$28,720.90

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2005

Airfield Manager: CLINT ANELON, 907-571-7171

NEEDS:

Surfaces:

Resurface gravel runway, taxiway, and apron

Dimensional:

Expand runway to 4,200' x 75'

Extend runway to 3,280' x 75'

Expand RSAs

Facilities:

Construct a new SREB

Equipment:

Grader & loader with attachments

Comments:

KOLIGANEK (JZZ)

Runway(s): 09/27 - 3000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 663

Borough: Dillingham

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$1,480.00

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$40,274.40

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1994

Airfield Manager: NORMAN HEYANO, 907-842-5511

NEEDS:

Surfaces:

Rehabilitate runway, taxiway, and apron surfaces

Remediate existing airport embankments

Dimensional:

Facilities:

Build a heated SREB

Rehabilitate the existing SREB

Equipment:

Grader & loader with attachments

Comments:

KONGIGANAK (DUY)

Runway(s): 01/19 - 2400' x 75'

Surface: Dirt/Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 3,947

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$22,658.07

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2010

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

Construct a new apron and segmented circle

Dimensional:

Extend runway in accordance to B-1 standards, but not to exceed 3,300'

Facilities:

Equipment:

Grader

Comments:

Airport needs culvert replacements, lighting system, fence/gate repairs, striping, signage, storm drainage, and updated Master Plan.

KOTLIK (2A9)

Runway(s): 02/20 - 4400' x 100'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 4,035

Borough: Wade Hampton

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$86,257.09

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1995

Airfield Manager: HARRY JOHNSON, JR., 907-624-3261

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Dozer Crawler 8-10T -- \$350,000

U/V Plow Grader/Loader -- \$350,000

Grader 34,000# -- \$350,000

Comments:

KOTZEBUE SPB (K36)

Runway(s): N/S

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification:

Enplanements:

Borough: Northwest Arctic

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road:

Last Major Improvement:

Airfield Manager: CALVIN SCHAEFFER, 907-442-3147

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

KOYUK (KKA) - Koyuk Alfred Adams

Runway(s): 01/19 - 3000' x 60' **Surface:** Gravel **Lighting:** BCN/Rwy_Lts/VASI
NAVAIDS: NDB/DME

Classification: Community	# Enplanements: 2,413	Borough: Nome
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$-
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$81,151.52
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 1991

Airfield Manager: HARRY JOHNSON, JR, 907-624-3261

NEEDS:

Surfaces:

Koyuk Airport Improvements -- \$13,500,000

Dimensional:

Facilities:

Koyuk SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

Lengthen the runway to 3,400', grade and resurface the existing runway, taxiway and apron, apply a dust palliative, remove existing obstructions and upgrade the lighting system.

KOYUKUK (KYU)

Runway(s): 06/24 - 4000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL

NAVAIDS: N/A

Classification: Community

Enplanements: 1,009

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$85,520.19

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2003

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

KWETHLUK (KWT)

Runway(s): 18/36 - 3199' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 3,579

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$21,975.13

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2001

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

Construct a new 2,400' x 60' gravel crosswind runway

Construct a new 2,980' x 120' RSA

Dimensional:

Facilities:

Construct a 1-bay heated SREB with floor

Equipment:

30,000 LB GRADER

Purchase a new CAT D-4 dozer

Comments:

KWIGILLINGOK (GGV)

Runway(s): 15/33 - 1835' x 40'

Surface: Dirt/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 3,625

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$22,403.47

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2011

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

Rehabilitate runway, taxiway, and apron surfaces

Dimensional:

Expand existing runway to 3,300' x 60'

Facilities:

Construct two 1-bay SREBs

Equipment:

Grader

Comments:

Tree removal mostly around windsock and approach ends (M&O DM)

Add 6 tiedowns (M&O DM)

LAKE LOUISE (Z55)

Runway(s): 3/31 - 3000' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Matanuska-Susitna

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$100.00

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 2010

Airfield Manager: JOHN HOFFMAN, 907-822-3222

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

LARSEN BAY (2A3)

Runway(s): 04/22 - 2690' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 2,753

Borough: Kodiak Island

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$17,678.18

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1993

Airfield Manager: ROB GREENE, 907-487-4952

NEEDS:

Surfaces:

Dimensional:

Facilities:

Construct a new 1-bay SREB

Equipment:

Grader, loader, snow removal equipment

Comments:

LEVELOCK (9Z8)

Runway(s): 01/19 - 3281' x 59'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL

NAVAIDS: N/A

Classification: Community

Enplanements: 408

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$27,041.41

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2003

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Grader, snow plow, loader wheel

Comments:

LIME VILLAGE (2AK)

Runway(s): 10/28 - 1500' x 55'

Surface: Dirt/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 9

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$550.00

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$19,219.31

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: DOUG LYMAN, 907-675-4345

NEEDS:

Surfaces:

Construct new community class airport

Construct runway (4000' x 75'), taxiway, apron (60,000 sqft), and RSA (4800' x 75')

Dimensional:

Facilities:

Snow removal equipment building

Construct 2-bay SREB 52' x 98' with beacon

Equipment:

Grader and loader

Comments:

LITTLE DIOMEDE ISLAND / IGNALUK (DM2)

Runway(s): Heliport - 64' x 64' **Surface:** Concrete **Lighting:** BCN/Boundary Lts
NAVAIDS: N/A

Classification: Community **# Enplanements:** 161 **Borough:** Nome
Air Carrier Hub: No **Medical Facility:** Yes **Annual Revenue:** \$-
USPS Hub: No **School Facility:** Yes **Ops Cost/Yr:** \$50,340.36
Part 139 Cert: No **On/Off Road:** Off **Last Major Improvement:**

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

Little Diomed Helipad Improvements -- \$1,800,000

Dimensional:

Facilities:

Little Diomed SRE Building Construction -- \$1,250,000

Equipment:

Comments:

Repair ice scour damage to helipad embankment, replace riprap and upgrade the lighting system.

LIVENGOOD (4AK) - Livengood Camp

Runway(s): 15/33 - 1415' x 50'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 2

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$675.88

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$40,085.25

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: JEFF RUSSELL, 907-451-2207

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

Extend and widen the Livengood Airport runway to 3,400 feet by 75 feet.

MANLEY HOT SPRINGS (MLY)

Runway(s): 02/20 - 2850' x 20'

Surface: Turf/Dirt

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 49

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$4,575.58

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 2012

Airfield Manager: JEFF RUSSELL, 907-451-2207

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

MANOKOTAK (MBA)

Runway(s): 03/21 - 3300' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 11,828

Borough: Dillingham

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$2,765.73

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$61,638.67

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2007

Airfield Manager: NORMAN HEYANO, 907-842-5511

NEEDS:

Surfaces:

Construct a new runway, RSA, and apron

Dimensional:

Facilities:

Equipment:

Grader, loader, snow plow attachments

Comments:

MARSHALL (MDM) - Marshall Don Hunter Sr.

Runway(s): 07/25 - 3200' x 100' **Surface:** Gravel **Lighting:** BCN/Rwy_Lts/REIL
NAVAIDS: N/A

Classification: Community	# Enplanements: 3,376	Borough: Wade Hampton
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$-
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$45,019.80
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 1999

Airfield Manager: ERIK WEINGARTH, 907-438-2416

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Grader 34,000# -- \$350,000

U/V Plow Grader/Loader -- \$350,000

Dozer Crawler 8-10T -- \$350,000

Comments:

MAY CREEK (MYK)

Runway(s): 13/31 - 2700' x 100'

Surface: Turf/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 15

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: JOHN HOFFMAN, 907-822-3222

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

MCCARTHY (I5Z)

Runway(s): 01/19 - 3500' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 50

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$6,639.14

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$17,019.11

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1999

Airfield Manager: JOHN HOFFMAN, 907-822-3222

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

MCGRATH (MCG)

Runway(s): 16/34 - 5936' x 100'

Surface: Asphalt

Lighting: BCN/Rwy_Lts/VASI/REIL

NAVAIDS:

LOC/DME/VORTAC

Classification: Regional

Enplanements: 5,519

Borough: Yukon-Koyukuk

Air Carrier Hub: Yes

Medical Facility: Yes

Annual Revenue: \$64,704.77

USPS Hub: Yes

School Facility: Yes

Ops Cost/Yr: \$263,372.74

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2006

Airfield Manager: DOUG LYMAN, 907-524-3241

NEEDS:

Surfaces:

Rehabilitate runway, taxiway, and apron pavement

Construct a new 300,000 sqft GA apron

Dimensional:

Extend runway 07/25 to 2,500'

Facilities:

Construct a 60' x 80' sand storage building

Equipment:

Snow plow, grader, snow blower, dump truck, snow attachments

Comments:

MEKORYUK SPB (MYU)

Runway(s): 05/23 - 3070' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/VASI/REIL

NAVAIDS: NDB/DME

Classification: Community

Enplanements: 1,464

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$54,597.85

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1984

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

Construct a new segment circle

Resurface runway and build crosswind runway

Dimensional:

Extend the existing runway to 4,000' and expand RSA accordingly

Facilities:

Upgrade or construct heated SREB

Equipment:

Loader wheel, grader, bulldozer, snow attachments, snow blower

Comments:

Design is complete for AIP funded airport rehabilitation and extension improvements, but ROW acquisition is dependent upon the condemnation of one Native Allotment, which is being considered. Also needs lighting installed and Master Plan update.

METLAKATLA SPB (MTM)

Runway(s): E/W, N/S - 5000' x 5000' **Surface:** Water **Lighting:** N/A
NAVAIDS: N/A

Classification: Community	# Enplanements: 3,657	Borough: Prince of Wales
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue:
USPS Hub: No	School Facility: Yes	Ops Cost/Yr:
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 2004

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

FY'18 Seaplane Float Rehab/Reconfiguration -- \$1,000,000

Dimensional:

Facilities:

Equipment:

Comments:

MEYERS CHUCK SPB (84K)

Runway(s): NW/SE - 7000' x 200'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 159

Borough: Ketchikan Gateway

Air Carrier Hub: No

Medical Facility: No

Annual Revenue:

USPS Hub: No

School Facility: No

Ops Cost/Yr:

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

MINCHUMINA (MHM)

Runway(s): 03/31 - 4184' x 100'

Surface: Gravel

Lighting: BCN/Rwy_Lts/PAPI

NAVAIDS: NDB

Classification: Local

Enplanements: 130

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$1,497.00

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$80,975.61

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Minchumina Airport Improvements -- \$5,000,000

Dimensional:

Facilities:

Minchumina SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

Resurface runway, apron and taxiway, remove obstructions, apply a dust palliative and install new lighting.

MINTO (51Z) - Minto Al Wright

Runway(s): 02/20 - 3400' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 160

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$9,173.10

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 2007

Airfield Manager: JEFF RUSSELL, 907-451-2207

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

MOUNTAIN VILLAGE (MOU)

Runway(s): 02/20 - 3501' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 5,299

Borough: Wade Hampton

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$1,326.25

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$73,337.33

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2004

Airfield Manager: ERIK WEINGARTH, 907-438-2416

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Dozer Crawler 8-10T -- \$350,000

Comments:

NAKNEK (5NK)

Runway(s): 08/26 - 1950' x 50'
14/32 - 1850' x 45'

Surface: Gravel
NAVAIDS: N/A

Lighting: BCN/Rwy_Lts

Classification: Local

Enplanements: 120

Borough: Bristol Bay

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$20,915.45

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

Fix road and runway separation

Construct a new 3,200' x 60' primary runway w/ 3,680' x 120' RSA

Construct two aprons - 80 parking spaces

Relocate runway 14/32 to correct safety, structural problems

Dimensional:

Facilities:

Construct a new regulator building

Construct new SREB

Equipment:

Grader, snow blower, loader, snow removal attachments

Comments:

NANWALEK (KEB) - English Bay

Runway(s): 01/19 - 1850' x 50'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 2,696

Borough: Kenai Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$15,750.35

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: KEVIN JONES, 907-235-8872

NEEDS:

Surfaces:

Construct airport parking apron

Shape and compact runway and taxiway (M&O DM)

Dimensional:

Facilities:

Construct new SREB

Equipment:

Comments:

NAPAKIAK (WNA)

Runway(s): 16/34 - 3248' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 2,075

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$17,921.52

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2003

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Grader, loader, snow plow attachments

Comments:

NAPASKIAK (PKA)

Runway(s): 02/20 - 3000' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 2,052

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$17,225.22

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1991

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

Dimensional:

Facilities:

Construct a 1-bay heated SREB with floor

Construct a terminal building

Equipment:

Grader, loader, snow plow attachments

Comments:

NELSON LAGOON (OUL)

Runway(s): 08/26 - 4003' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 316

Borough: Aleutians East

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$41,471.27

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1996

Airfield Manager: JEFF DOERNING, 907-532-5000

NEEDS:

Surfaces:

Dimensional:

Facilities:

Construct a new 1-bay SREB

Equipment:

Grader, loader, snow plow, motor grader

Comments:

Requires land acquisition, updated Master Plan, FAA navigation equipment improvements, gate/fence repairs, and MALSR install.

NEW STUYAHOK (KNW)

Runway(s): 14/32 - 3281' x 98'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 1,288

Borough: Dillingham

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$550.00

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$46,817.60

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2006

Airfield Manager: NORMAN HEYANO, 907-842-5511

NEEDS:

Surfaces:

Dimensional:

Expand the runway to 5,000' x 100'

Expand the RSAs

Facilities:

Equipment:

Grader, loader, snow removal attachments

Comments:

NEWTOK (EWU)

Runway(s): 15/33 - 2202' x 35'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 2,352

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$24,768.33

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1994

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

Construct a new airport at Mertarvik (currently village is impacted by river erosion)

Construct 3,300' x 100' runway

Dimensional:

Facilities:

1 heated SREB building

1 unheated SREB building

Equipment:

Purchase a Cat D4 dozer

Purchase a new CAT 140 grader

Comments:

Install MIRL and airport lighting

Construct a 2,150' x 12' airport access road

Purchase 225 acres of land

NIGHTMUTE (IGT)

Runway(s): 03/21 - 3180' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL

NAVAIDS: N/A

Classification: Community

Enplanements: 1,646

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$34,284.91

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2007

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

Construct an aircraft parking apron, apron access, and segmented circle

Dimensional:

Expand the runway to 3,200' x 75' and RSA to 3,800' x 120'

Facilities:

Equipment:

Loader and grader

Comments:

Requires lighting/MIRL install, culverts, brush/tree clearing

NIKOLAI (FSP)

Runway(s): 04/32 - 4003' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 625

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$35,502.31

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2001

Airfield Manager: DOUG LYMAN, 907-745-2159

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Grader, loader, and snow removal attachments

Comments:

NINILCHIK (NIN)

Runway(s): 10/28 - 2400' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 4

Borough: Kenai Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$4,500.00

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$1,702.60

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: CARL HIGH, 907-262-2199

NEEDS:

Surfaces:

Minor gravel resurfacing (M&O DM)

Runway and RSA grading (M&O DM)

Dimensional:

Facilities:

Equipment:

SANDER 8CY STAINLESS

Comments:

NOATAK (WTK)

Runway(s): 01/19 - 3992' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 4,549

Borough: Northwest Arctic

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$1,315.68

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$110,984.02

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1992

Airfield Manager: CALVIN SCHAEFFER, 907-442-3147

NEEDS:

Surfaces:

Dimensional:

Noatak Airport Relocation -- \$13,000,000

Facilities:

Equipment:

Grader 34,000# -- \$350,000

Loader Wheeled 1.5CY -- \$350,000

Comments:

Relocate the existing 4,000' x 60' airport, construct a new runway, apron, taxiway, aviation support area, SREB, apply a dust palliative and construct a new airport access road.

NOME (94Z) - Nome City Field

Runway(s): 03/21 - 1950' x 110'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$8,745.65

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$6,204.18

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: ROBERT MADDEN, 907-443-3431

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

NONDALTON (5NN)

Runway(s): 02/20 - 2800' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 1,329

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$40,258.02

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2003

Airfield Manager: CLINT ANELON, 907-571-7171

NEEDS:

Surfaces:

Resurface gravel runway

Dimensional:

Facilities:

Equipment:

Loader, grader, and snow removal attachments

Comments:

NOORVIK (D76) - Robert/Bob/Curtis Memorial

Runway(s): 06/24 - 4000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 4,065

Borough: Northwest Arctic

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$67,230.58

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2001

Airfield Manager: CALVIN SCHAEFFER, 907-442-3147

NEEDS:

Surfaces:

Noorvik Airport Rehabilitation -- \$9,000,000

Dimensional:

Facilities:

Noorvik SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

Repair runway shoulders, repair all airport operating surfaces and apply dust palliative.

NORTHWAY (ORT)

Runway(s): 05/23 - 5100' x 100' **Surface:** Asphalt/Grooved **Lighting:** BCN/Rwy_Lts/REIL/PAPI
NAVAIDS: VORTAC/NDB

Classification: Community	# Enplanements: 3	Borough: Fairbanks/North Star
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$3,557.50
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$45,204.72
Part 139 Cert: No	On/Off Road: On	Last Major Improvement:

Airfield Manager: DENNIS BISHOP, 907-883-5128

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Snowwing Grader -- \$350,000

U/V Plow Grader/Loader -- \$350,000

Grader Rural Airport Series 160M2 -- \$350,000

Comments:

NULATO (NUL)

Runway(s): 02/20 - 4000' x 100'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 2,914

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$89,770.34

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2010

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

NUNAM IQUA (SXP) - Sheldon Point

Runway(s): 01/19 - 3015' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 1,181

Borough: Wade Hampton

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$145,486.99

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: HARRY JOHNSON, 907-624-326

NEEDS:

Surfaces:

Nunam Iqua Airport Runway Rehabilitation -- \$14,000,000

Dimensional:

Facilities:

Nunam Iqua Airport Access Road Construction -- \$3,000,000

Equipment:

Comments:

Widen and extend the runway at Sheldon Point to at least 3,400' x 100' and lighting and grading improvements.

NUNAPITCHUK (16A)

Runway(s): 18/36 - 2420' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 3,482

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$13,206.78

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2007

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

Construct a 2,900' x 150' RSA

Construct a new 350' x 79' taxiway safety area

Construct a new 60,00 sq ft apron

Construct a new 20,000 sq ft aviation support area

Construct a new 15,400 sq ft segmented circle

Construct embankments for future PAPI's and REIL's

Dimensional:

Expand runway to 2,300' x 60'

Expand runway to 3,280' x 75'

Expand the apron to 60,000 sqft

Facilities:

Construct 2 each 24' x 48' SREB (1 heated/1 unheated)

Installed 2 fuel storage tanks on the aviation support area

Equipment:

Grader, loader, snow removal attachments

Comments:

OLD HARBOR (6R7)

Runway(s): 03/21 - 2750' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 3,239

Borough: Kodiak Island

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$895.00

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$12,126.79

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1992

Airfield Manager: ROB GREENE, 907-487-4952

NEEDS:

Surfaces:

Resurface runway

Dimensional:

Expand the runway to 3,300' x 75'

Facilities:

Construct a new 1-bay SREB

Equipment:

Grader, loader, snow removal attachments

Comments:

OPHIR (Z17)

Runway(s): 11/29 - 2520' x 100'

Surface: Turf/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 17

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue:

USPS Hub: No

School Facility: No

Ops Cost/Yr:

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: MICHAEL FLEAGLE, 907-524-3241

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

OUZINKIE (4K5)

Runway(s): 08/26 - 3300' x 60'

Surface: Gravel

Lighting: BCN

NAVAIDS: N/A

Classification: Community

Enplanements: 3,309

Borough: Kodiak Island

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$24,938.62

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2011

Airfield Manager: ROB GREENE, 907-487-4952

NEEDS:

Surfaces:

Relocate the airport site 1.7 miles north

Construct a runway 3,300' X 75' and RSA 3,900' x 150'

Construct a 60,000 sq ft apron, 30,000 sq ft aviation support area

Construct a 10,000 sq.ft. maintenance and operations pad

Dimensional:

Facilities:

Equipment:

Grader, loader, snow removal attachments

Comments:

Due to the low population, 26 in 2012, the cost to reconstruct the airport will be extremely high. Needs extended edge lighting, beacon, lighted windsock, and improved airport access road. Bridge and access road improvements may be shared with FHWA funded project.

PEDRO BAY (4K0)

Runway(s): 09/27 - 3000' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL

NAVAIDS: N/A

Classification: Community

Enplanements: 590

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$69,685.21

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1995

Airfield Manager: CLINT ANELON, 907-571-7171

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Grader, loader, snow removal attachments

Comments:

PERRYVILLE (PEV)

Runway(s): 02/20 - 3300' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 734

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$16,302.98

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2005

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Grader, loader, snow removal attachments, loader wheel

Aviation radio

Comments:

PETERSBURG (PSG) - Petersburg James A. Johnson

Runway(s): 05/23 - 6400' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/App_Lts/REIL/PAPI
NAVAIDS: LDA/DME/NDB

Classification: Regional	# Enplanements: 18,318	Borough: Wrangell
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$33,784.00
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$385,032.54
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2009

Airfield Manager: TED SOKOL, 907-772-4624

NEEDS:

Surfaces:

FY'15 Apron/TWY Rehab -- \$3,000,000

Dimensional:

Facilities:

FY'22 Access Road Realignment, Parking, ROW -- \$3,200,000

Equipment:

FY'18 ARFF Truck -- \$1,000,000

Comments:

PETERSBURG SPB (63A) - Lloyd R. Roundtree Seaplane Facility

Runway(s): NE/SW - 9000' x 1100'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Wrangell

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$7,518.38

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1995

Airfield Manager: TED SOKOL, 907-772-4624

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

PILOT POINT (PNP)

Runway(s): 07/25 - 3280' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 692

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$21,529.87

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2003

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

Dimensional:

Expand the runway to 5,050' x 100'

Expand the RSAs

Facilities:

Equipment:

Grader, loader wheel, snow plow, snow removal attachments

Comments:

PILOT STATION (OAK)

Runway(s): 07/25 - 2541' x 55'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 3,641

Borough: Wade Hampton

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$55,917.92

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1996

Airfield Manager: ERIK WEINGARTH, 907-438-2416

NEEDS:

Surfaces:

Pilot Station Airport Relocation -- \$15,700,000

Dimensional:

Facilities:

Equipment:

Loader Wheeled 1.5 CY -- \$350,000

Comments:

Relocate the airport at Pilot Station away from the community.

PLATINUM (PTU)

Runway(s): 14/32 - 3300' x 75'

Surface: Gravel

Lighting: BCN

NAVAIDS: N/A

Classification: Community

Enplanements: 1,139

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$35,055.92

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2009

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

Construct new runway (3,280' x 75'), taxiway, and apron

Dimensional:

Expand runway to 3,280' x 75'

Facilities:

Equipment:

Loader, snow plow, snow removal attachments

Comments:

POINT BAKER SPB (63A)

Runway(s): N/S - 4000' x 250'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 23

Borough: Prince of Wales

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$2,723.12

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1994

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

POINT HOPE (PHO)

Runway(s): 01/19 - 3992' x 75'	Surface: Asphalt	Lighting: BCN/Rwy_Lts/VASI
	NAVAIDS: NDB	
Classification: Community	# Enplanements: 4,484	Borough: North Slope
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$988.75
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$104,534.01
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 1992

Airfield Manager: CALVIN SCHAEFFER, 907-442-3147

NEEDS:

Surfaces:

Point Hope Airport Pavement Rehabilitation -- \$7,000,000

Dimensional:

Facilities:

Equipment:

Comments:

Rehabilitate all pavement surfaces.

PORT ALEXANDER SPB (AHP)

Runway(s): N/S - 3000' x 300'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 176

Borough: Wrangell

Air Carrier Hub: No

Medical Facility: No

Annual Revenue:

USPS Hub: No

School Facility: Yes

Ops Cost/Yr:

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

PORT GRAHAM (PGM)

Runway(s): 12/30 - 1875' x 45'

Surface: Dirt/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 2,167

Borough: Kenai Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$19,702.85

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: KEVIN JONES, 907-235-8872

NEEDS:

Surfaces:

Construct airport parking apron

Airport relocation

Dimensional:

Facilities:

Construct new SREB

Equipment:

30,000 LB GRADER

Comments:

PORT HEIDEN (PTH)

Runway(s): 05/23 - 5000' x 100'
13/31 - 4000' x 100'

Surface: Gravel
NAVAIDS: NDB/DME

Lighting: BCN/Rwy_Lts/VASI/
REIL/PAPI

Classification: Community

Enplanements: 1,149

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$2,171.11

USPS Hub: Yes

School Facility: Yes

Ops Cost/Yr: \$53,070.40

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2003

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

ARFF vehicle, loader wheel, grader, snow blower, snow attachments

Aviation radio

Comments:

PORT LIONS (ORI)

Runway(s): 07/25 - 2200' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 2,463

Borough: Kodiak Island

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$26,082.48

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2011

Airfield Manager: ROB GREENE, 907-487-4952

NEEDS:

Surfaces:

Construct apron and taxiway

Reconstruct or relocate airport

Dimensional:

Rotate the airport

Extend the airport

Facilities:

Construct a new 2-bay heater SREB

Construct a new regulator building

Equipment:

Loader, directional snow plow

Comments:

Airport needs erosion control, improved drainage, brush cutting, utility modifications, updated lease-lot mx, and new airport access road.

PORT PROTECTION SPB (19P)

Runway(s): NW/SE

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 68

Borough: Prince of Wales

Air Carrier Hub: No

Medical Facility: No

Annual Revenue:

USPS Hub: No

School Facility: Yes

Ops Cost/Yr:

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

FY'19 Replace seaplane float -- \$600,000

Dimensional:

Facilities:

Equipment:

Comments:

PORTAGE CREEK (A14)

Runway(s): 10/28 - 1920' x 60'
01/19 - 1470' x 60'

Surface: Dirt/Gravel
NAVAIDS: N/A

Lighting: N/A

Classification: Local

Enplanements: 16

Borough: Dillingham

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$18,404.72

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1984

Airfield Manager: NORMAN HEYANO, 907-842-3422

NEEDS:

Surfaces:

Dimensional:

Facilities:

Demolish existing 1-bay SREB

Construct a new 2-bay heater SREB

Equipment:

Grader with wing attachment

Purchase an aviation radio

Comments:

PROSPECT CREEK (PPC)

Runway(s): 01/19 - 4968' x 150'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: NDB

Classification: Local

Enplanements: 546

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$-

Part 139 Cert: Yes

On/Off Road:

Last Major Improvement:

Airfield Manager: JEFF RUSSELL, 907-451-2207

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

QUARTZ CREEK (5QC) - Kougarak

Runway(s): 12/30 - 2960' x 64'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Nome

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$550.00

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$2,651.73

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

Quartz Creek Airport Improvements -- \$500,000

Dimensional:

Facilities:

Equipment:

Comments:

Rehabilitate airport for all-season operations, including runway surface repairs and vegetation clearing.

RAMPART (RMP)

Runway(s): 11/29 - 3520' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Local

Enplanements: 176

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$107,850.38

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2001

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Dimensional:

Facilities:

SRE Building Replacement -- \$2,000,000

Equipment:

Dozer Crawler 8-10T -- \$350,000

Comments:

RED DEVIL (RDV)

Runway(s): 10/28 - 4820' x 75'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 77

Borough: Bethel

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$550.00

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$12,453.56

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2005

Airfield Manager: TERRY HOFFMAN, 907-675-4345

NEEDS:

Surfaces:

Construct a new taxiway and apron

Dimensional:

Facilities:

Equipment:

Grader, bulldozer, loader wheel, snow attachments

Comments:

RUBY (RBY)

Runway(s): 03/21 - 4000' x 100'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 2,203

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$307,897.30

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1992

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Ruby Aiport Improvements -- \$6,000,000

Dimensional:

Facilities:

Equipment:

Comments:

Airport Imp-Resurface runway, apron and taxiway, apply a dust palliative and upgrade the lighting system.

RUSSIAN MISSION (RSH)

Runway(s): 17/35 - 3620' x 100'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 2,916

Borough: Wade Hampton

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$72,385.60

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2000

Airfield Manager: ERIK WEINGARTH, 907-438-2416

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Grader 34,000# -- \$350,000

U/V Plow Grader/Loader -- \$350,000

Comments:

SAINT GEORGE (PBV)

Runway(s): 11/29 - 4982' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/App_Lts/HIRL/REIL/PAPI
NAVAIDS: ILS/NDB

Classification: Community	# Enplanements: 523	Borough: Aleutians West
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$1,030.00
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$176,075.42
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 2005

Airfield Manager: NORMAN HEYANO, 907-842-5511

NEEDS:

Surfaces:

Pave runway 11/29 taxiway and apron

Dimensional:

Extend safety areas

Facilities:

Construct heated SREB

Equipment:

Loader wheel, grader, loader, plow attachments, pickup, snow blower

Comments:

SAINT MICHAEL (SMK)

Runway(s): 02/20 - 4000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 2,631

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$68,319.20

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: HARRY JOHNSON, 907-624-3261

NEEDS:

Surfaces:

Saint Michael Airport Improvements -- \$8,300,000

Dimensional:

Facilities:

SRE Building Upgrade -- \$825,000

Equipment:

Snowwing Grader -- \$350,000

U/V Plow Grader/ Loader -- \$350,000

U-Blade Loader 10CY -- \$350,000

Grader 30,000# -- \$350,000

Loader Wheeled 1.5CY -- \$350,000

Comments:

Rehabilitate the runway, taxiway, apron and airport lighting, stabilize slopes, rehabilitate shoulders, apply dust palliative, and repair and resurface the airport access road.

SAINT PAUL ISLAND (SNP)

Runway(s): 18/36 - 6500' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/App_Lts/HIRL/VASI
NAVAIDS: ILS/DME/NDB

Classification:	Community	# Enplanements:	2,830	Borough:	Aleutians West
Air Carrier Hub:	No	Medical Facility:	Yes	Annual Revenue:	\$1,225.00
USPS Hub:	No	School Facility:	Yes	Ops Cost/Yr:	\$205,428.91
Part 139 Cert:	No	On/Off Road:	Off	Last Major Improvement:	2004

Airfield Manager: JERRY MERCULIEF, 907-546-2331

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

ARFF vehicle, rotary plow, grader, loader wheel, pickup, tow vehicle, snow blower

Comments:

SALMON LAKE (Z81)

Runway(s): 15/33 - 1860' x 55'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Nome

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$5,043.79

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

SAND POINT (SDP)

Runway(s): 13/31 - 5213' x 150'

Surface: Asphalt

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: NDB

Classification: Community

Enplanements: 4,843

Borough: Aleutians East

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$10,485.99

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$79,933.69

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2005

Airfield Manager: JEFF DOERNING, 907-532-5000

NEEDS:

Surfaces:

Pave and remark runway and RSA

Dimensional:

Extend runway to 4,100' and embankment 700' to the south

Shift runway centerline 30' east and 300' south

Extend RSA

Facilities:

Demolish existing sand storage building and attach freight office build

Construct new heated sand storage building with concrete floor, 400 cubic yard capacity

Construct a new 2-bay SRE/ARFF building w/ 16' wide doors, an office/training room, a restroom/shower/laundry facility and 3000 gallon water tank/pump

Equipment:

Loader wheel, snow blower, minivan, grader

Comments:

Install perimeter fencing

SAVOONGA (SVA)

Runway(s): 05/23 - 4400' x 100'

Surface: Gravel

Lighting: BCN/Rwy_Lts/PAPI

NAVAIDS: VOR/DME

Classification: Community

Enplanements: 4,083

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: Yes

School Facility: Yes

Ops Cost/Yr: \$147,004.66

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2009

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

Savoonga Airport Improvements -- \$5,000,000

Dimensional:

Facilities:

Equipment:

Comments:

Rehabilitate and resurface runways, taxiways, and apron, and replace airport lighting.

SCAMMON BAY (SCM)

Runway(s): 10/28 - 3000' x 75'

Surface: Dirt

Lighting: BCN/Rwy_Lts/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 4,510

Borough: Wade Hampton

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$36,562.37

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2003

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

Dimensional:

Facilities:

Construct a new SREB

Equipment:

grader, snow blower, loader wheel, bulldozer, snow attachments

Comments:

SELAWIK (WLK)

Runway(s): 04/22 - 3002' x 60'
09/27 - 2659' x 60'

Surface: Gravel
NAVAIDS: VOR/DME

Lighting: BCN/Rwy_Lts/VASI/PAPI

Classification: Community

Enplanements: 4,922

Borough: Northwest Arctic

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$82,193.13

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1998

Airfield Manager: CALVIN SCHAEFFER, 907-442-3147

NEEDS:

Surfaces:

Dimensional:

Selawik Airport Runway Extension -- \$12,000,000

Facilities:

Selawik SRE Building Upgrade -- \$500,000

Equipment:

Comments:

Expand the existing runway at Selawik to at least 3,400' x 75' and complete electrical and grading improvements.

SELDOVIA (SOV)

Runway(s): 16/34 - 1845' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 4,538

Borough: Kenai Peninsula

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$9,905.00

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$55,941.94

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2009

Airfield Manager: KEVIN JONES, 907-234-7818

NEEDS:

Surfaces:

Pave runway and apron

Reconstruct or relocate the airport

Dimensional:

Expand RSA on approach end of runway 16 to 300'

Facilities:

Equipment:

Loader wheel, snow blower, snow removal attachments

Comments:

SEWARD (SWD)

Runway(s): 13/31 - 4533' x 100'
16/34 - 2289' x 75' **Surface:** Asphalt **Lighting:** BCN/Rwy_Lts/VASI
NAVAIDS: N/A

Classification: Community **# Enplanements:** 8 **Borough:** Kenai Peninsula
Air Carrier Hub: No **Medical Facility:** Yes **Annual Revenue:** \$13,137.53
USPS Hub: No **School Facility:** Yes **Ops Cost/Yr:** \$34,615.83
Part 139 Cert: No **On/Off Road:** On **Last Major Improvement:** 1991

Airfield Manager: CARL HIGH, 907-224-3086

NEEDS:

Surfaces:

- Reconstruct both runways at higher elevation
- Increase erosion protection entire length of 12/30
- Repave taxiways and apron
- Construct helipad and public parking
- Construct public parking

Dimensional:

- Displace threshold of runway 30 to 100' north
- Widen taxiway A

Facilities:

- Construct a 4-bay SREB
- Construct a regulator building

Equipment:

- Dump truck, deicing truck, grader, loader, snow removal attachments

Comments:

SHAGELUK (SHX)

Runway(s): 16/34 - 3400' x 75'

Surface: Gravel

Lighting: BCN/App-Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 634

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$68,174.49

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2000

Airfield Manager: ERIK WEINGARTH, 907-438-2416

NEEDS:

Surfaces:

Dimensional:

Facilities:

Shageluk SRE Building Replacement -- \$2,000,000

Equipment:

Grader 34,000# -- \$350,000

U/V Plow Grader/ Loader -- \$350,000

Dozer Crwlr 8-10T -- \$350,000

Comments:

Reconstruct the 4-mile airport access road to include embankment stabilization, minor realignment and resurfacing.

SHAKTOOLIK (2C7)

Runway(s): 14/32 - 4001' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 2,078

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$64,597.40

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1998

Airfield Manager: HARRY JOHNSON, 907-624-3261

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

SHEEP MOUNTAIN (SMU)

Runway(s): 05/23 - 2270' x 10'

Surface: Dirt/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Matanuska-Susitna

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: NEAL HENSLEE, 907-745-5116

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

SHISHMAREF (SHH)

Runway(s): 05/23 - 4997' x 75'

Surface: Asphalt

Lighting: BCN/Rwy_Lts/VASI

NAVAIDS: NDB

Classification: Community

Enplanements: 2,989

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$2,499.55

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$136,752.15

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1992

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

Resurface the runway, taxiway, and apron at the Shishmaref Airport.

SHUNGNAK (SHG)

Runway(s): 09/27 - 4001' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 1,955

Borough: Northwest Arctic

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$2,307.52

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$56,141.26

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1996

Airfield Manager: CALVIN SCHAEFFER, 907-442-3147

NEEDS:

Surfaces:

Dimensional:

Facilities:

Shungnak SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

SITKA (SIT) - Sitka Rocky Gutierrez

Runway(s): 11/29- 6500' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/HIRL/VASI/REIL
NAVAIDS:
LDA/DMA/VORTAC

Classification: Regional	# Enplanements: 65,193	Borough: Sitka
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$44,108.83
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$799,479.72
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2011

Airfield Manager: DAVE LUCHINETTI, 907-966-2960

NEEDS:

Surfaces:

Dimensional:

FY'16 GA Apron Development (Charcoal Island)-- \$3,000,000

FY'18 Construct Partial Parallel TWY -- \$32,600,000

FY'18 Expand GA Apron and Lease Lots -- \$5,000,000

Facilities:

FY'16 Property Acquisition -- \$1,100,000

Equipment:

FY'15 Plow Trucks (2) -- \$1,000,000

FY'17 Loader and Trap Plow -- \$450,000

FY'19 ARFF Truck -- \$1,000,000

Comments:

SKAGWAY (SGY)

Runway(s): 02/20 - 3500' x 75'

Surface: Asphalt

Lighting: Rwy_Lts/REIL

NAVAIDS: N/A

Classification: Community

Enplanements: 8,244

Borough: Skagway

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$28,038.25

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$42,347.72

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1999

Airfield Manager: MISSY TYSON, 907-983-2323

NEEDS:

Surfaces:

Dimensional:

Facilities:

FY'15 Property Acquisition -- \$200,000

Equipment:

Comments:

SKWENTNA (SKW)

Runway(s): 10/28 - 3400' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Local

Enplanements: 139

Borough: Matanuska-Susitna

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$1,467.50

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$63,509.67

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1987

Airfield Manager: NEAL HENSLEE, 907-745-2159

NEEDS:

Surfaces:

Dimensional:

Facilities:

Move the existing maintenance shop and generator

Construct a new two-bay SREB

Provide a 10k generator for lighting

Equipment:

Grader, loader wheel, snow blower

Comments:

SLEETMUTE (SLQ)

Runway(s): 14/32 - 3100' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 377

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$33,874.68

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: TERRY HOFFMAN, 907-675-4345

NEEDS:

Surfaces:

Resurface runway

Construct new apron and taxiway

Dimensional:

Facilities:

Demolish existing 1-bay SREB

Construct a new 2-bay heater SREB with floor

Equipment:

Grader, bulldozer, loader, snow attachments

Comments:

SOUTH NAKNEK (WSN)

Runway(s): 12/30 - 3314' x 60' 04/22 - 2264' x 60'	Surface: Dirt/Gravel NAVAIDS: N/A	Lighting: BCN/HIRL/VASI
Classification: Local	# Enplanements: 115	Borough: Dillingham
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$1,585.20
USPS Hub: No	School Facility: No	Ops Cost/Yr: \$24,948.62
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement: 1996

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

Rehabilitate runway, crosswind runway, and apron

Correct RSAs

Reconfigure displaced threshold

Dimensional:

Facilities:

Equipment:

Grader

Comments:

STEBBINS (WBB)

Runway(s): 05/23 - 2999' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 2,880

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$1,588.80

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$55,501.25

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1995

Airfield Manager: HARRY JOHNSON, 907-624-326

NEEDS:

Surfaces:

Dimensional:

Stebbins Airport Runway Extension -- \$3,000,000

Facilities:

Stebbins SRE Building Replacement -- \$2,000,000

Equipment:

Grader 34,000# -- \$350,000

Dozer Crawler 8-10T -- \$350,000

U/V Plow Grader/ Loader -- \$350,000

Comments:

Expand and widen the runway to 3,400' x 75', expand apron and taxiway, reduce obstructions, and apply dust palliative to the operational surfaces.

STEVENS VILLAGE (SVS)

Runway(s): 05/23 - 4000' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 793

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$96,856.81

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2005

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

STONY RIVER (SRV)

Runway(s): 18/36 - 2601' x 40'

Surface: Dirt/Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 174

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$24,624.04

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: TERRY HOFFMAN, 907-675-4345

NEEDS:

Surfaces:

Runway resurface

Construct a seperated apron and taxiway

Airport relocation

Dimensional:

Expand runway to 3,200' x 75'

Facilities:

Construct a temporary equipment building

Construct a SREB

Equipment:

Purchase a grader and dozer

Comments:

Airport requires lease lot acquisition, lighting improvements, floatplane dock, Master Plan update, removal of tree obstructions on rwy 21, and new access road to GA apron. Minor repair of the existing RWY with AIP Surface maintenance funding in 2012

SUMMIT (UMM)

Runway(s): 03/21 - 3840' x 80'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Matanuska-Susitna

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$24,325.02

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: TOM WILLIAMS, 907-451-5280

NEEDS:

Surfaces:

Summit Airport Improvements -- \$5,000,000

Dimensional:

Facilities:

Equipment:

Comments:

Rehabilitate and resurface runways, taxiways, and apron, apply a dust palliative and replace airport lighting.

TAKOTNA (TCT)

Runway(s): 04/22 - 3300' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 595

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$74,613.60

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2009

Airfield Manager: DOUG LYMAN, 907-524-3241

NEEDS:

Surfaces:

Construct a new 4,000' x 60' gravel runway

Construct a 4,600' x 150' RSA

Construct a 100,00 sqft apron and aviation support area

Construct a 25'-wide taxiway

Airport relocation

Dimensional:

Facilities:

Equipment:

Grader, loader, plow attachments

Comments:

Needs airport planning study

TALKEETNA (TKA)

Runway(s): 18/36 ' 3500' x 75'

Surface: Asphalt

Lighting: BCN/Rwy_Lts/VASI

NAVAIDS: VOR/DME

Classification: Community

Enplanements: 10

Borough: Matanuska-Susitna

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$55,188.57

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$108,579.52

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1996

Airfield Manager: STEVE HANSON, 907-733-2278

NEEDS:

Surfaces:

- Rehabilitate pavement on runway 18/36, taxiways, and apron
- Construct transient apron/embankment for future GA and lease lot development
- Expand the commercial and transient apron
- Construct a helipad, associated apron, and FSS parking

Dimensional:

- Expand commercial, GA and transient aircraft parking

Facilities:

Equipment:

- Snow blower, grader, loader wheel

Comments:

TANANA (TAL) - Ralph M. Calhoun Memorial

Runway(s): 07/25 - 4400' x 100'

Surface: Gravel

Lighting: BCN/Boundary Lts/VASI

NAVAIDS: VOR/DME/NDB

Classification: Community

Enplanements: 3,166

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$1,645.34

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$89,762.51

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2004

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Dimensional:

Facilities:

Tanana SRE Building Replacement -- \$2,000,000

Equipment:

Comments:

TATITLEK (7KA)

Runway(s): 13/31 - 3701' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 1,761

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$88,112.44

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1995

Airfield Manager: STEVE SEARLES, 907-835-5658

NEEDS:

Surfaces:

Dimensional:

Facilities:

Tatitlek SRE Building Replacement -- \$2,000,000

Equipment:

Snowwing Grader -- \$350,000

U/V Plow Grader/ Loader -- \$350,000

Grader 35,000# -- \$350,000

Comments:

TAZLINA (Z14)

Runway(s): 13/31 - 1200' x 40'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: JOHN HOFFMAN, 907-822-3222

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

TELLER (TER)

Runway(s): 07/25 - 3000' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 1,339

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$66,502.94

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1999

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

Dimensional:

Teller Airport Runway Extension and Crosswind Runway Construction -- \$5,000,000

Facilities:

Teller SRE Building Replacement -- \$2,000,000

Equipment:

Dozer Crawler 8-10T -- \$350,000

Comments:

Lengthen and widen the existing runway, construct a crosswind runway and install new lighting.

TENAKEE SPRINGS SPB (TKE)

Runway(s): E/W - 10000' x 7000'

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements: 689

Borough: Hoonah-Angoon

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2005

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

TETLIN (3T4)

Runway(s): 08/26 - 3300' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Fairbanks/North Star

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$5,135.75

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 2003

Airfield Manager: DENNIS BISHOP, 907-822-3222

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

THORNE BAY SPB (KTB)

Runway(s): NW/SE - 5000' x 2000' **Surface:** Water **Lighting:** N/A
NAVAIDS: N/A

Classification:	Community	# Enplanements:	2,621	Borough:	Prince of Wales
Air Carrier Hub:	No	Medical Facility:	Yes	Annual Revenue:	\$-
USPS Hub:	No	School Facility:	Yes	Ops Cost/Yr:	\$-
Part 139 Cert:	No	On/Off Road:	Off	Last Major Improvement:	

Airfield Manager: SHANE ULERY, HAR. MSTR., 907-828-3380

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

TOGIAK VILLAGE (TOG)

Runway(s): 03/21 - 4400' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/VASI/PAPI

NAVAIDS: NDB/DME

Classification: Community

Enplanements: 1,638

Borough: Dillingham

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$5,821.69

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$51,174.51

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: NORMAN HEYANO, 907-842-5511

NEEDS:

Surfaces:

Construct a new crosswind runway

Resurface gravel runways

Resurface gravel taxiways

Resurface gravel aprons

Dimensional:

Facilities:

Replace the existing 2-bay SREB with a heated 2-bay SREB with 20' wide doors, a rotating beacon, concrete floors with an oil-water separator system

Construct a separate electrical enclosure

Add two 1,000 gallon double wall fire rated fuel tanks

Construct a SREB

Equipment:

RURAL AIRPORT GRADER

3 CY LOADER WHEEL

SNOW BLOWER

Purchase a replacement loader with mounted snow blower

Comments:

TOK (6K8) - Tok Junction

Runway(s): 07/25 - 2509' x 50'

Surface: Asphalt

Lighting: BCN/Rwy_Lts/VASI

NAVAIDS: N/A

Classification: Community

Enplanements:

Borough: Valdez-Cordova

Air Carrier Hub: Yes

Medical Facility: Yes

Annual Revenue: \$9,959.74

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$15,269.90

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1999

Airfield Manager: DENNIS BISHOP, 907-883-5128

NEEDS:

Surfaces:

Dimensional:

Tok Airport Runway Expansion and Crosswind Runway Construction -- \$3,500,000

Facilities:

Visual Glide Slope Indicator Lighting Replacement -- \$2,500,000

Equipment:

Comments:

Lengthen and widen the existing runway, construct a crosswind runway and install new lighting.

TOKSOOK BAY (OOK)

Runway(s): 16/34 - 3218' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 4,338

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$1,530.00

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$19,742.47

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2001

Airfield Manager: DAVE CUMMINGS, 907-543-2492

NEEDS:

Surfaces:

Construct a new gravel crosswind runway

Construct a new RSA

Dimensional:

Facilities:

Construct a 1-bay heated SREB with floor

Equipment:

Dozer and grader

Comments:

Requires access road, utility relocation, NAVAID modification.

Develop, evaluate and present alternative concepts to reconstruct or relocate the airport. Products of this study will include an airport master plan, an environmental assessment, an airport layout plan, design level surveying, controlled aerial photography and geotechnical soils analysis of the preferred airport alternative.

TULUKSAK (TLT)

Runway(s): 15/33 - 3300' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 2,923

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$42,123.02

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2009

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

Airport relocation

Dimensional:

Facilities:

Specify, order, and setup a pre-fabricated temporary SREB

Equipment:

Purchase a snow removal equipment loader

Grader w/attachments

Loader w/attachments

Comments:

TUNTUTULIAK (A61)

Runway(s): 02/20 - 3025' x 90'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL

NAVAIDS: N/A

Classification: Community

Enplanements: 3,585

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$24,637.26

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2006

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

Construct runway, taxiway, apron, and associated RSA

Dimensional:

Facilities:

Construct 2-bay SREB

Equipment:

Loader wheel, loader, grader, and associated attachments

Comments:

TUNUNAK (4KA)

Runway(s): 08/26 - 1778' x 30'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 1,909

Borough: Bethel

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$38,679.77

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 2012

Airfield Manager: DAVE CUMMINGS, 907-543-2495

NEEDS:

Surfaces:

Relocate the existing Tununak airport

Construct runway, taxiway, and apron

Dimensional:

Extend runway

Expand apron

Facilities:

Build a new SREB

Equipment:

Grader, loader, snow plow, loader wheel

Comments:

TWIN HILLS (A63)

Runway(s): 18/36 - 3000' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 216

Borough: Dillingham

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$20,701.46

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1994

Airfield Manager: NORMAN HEYANO, 907-842-5511

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Grader, snow plow

Comments:

UGASHIK (9A8)

Runway(s): 06/24 - 3100' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements: 156

Borough: Lake & Peninsula

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$7,980.69

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: KYLER HYLTON, 907-246-3325

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Grader

Comments:

UMIAT (UMT)

Runway(s): 06/24 - 5583' x 100'

Surface: Gravel

Lighting: BCN

NAVAIDS: N/A

Classification: Local

Enplanements: 119

Borough: North Slope

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$33,067.50

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$215.41

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: JEREMY WORRALL, 907-451-5230

NEEDS:

Surfaces:

Dimensional:

Facilities:

Umiat Airport Lease Lot Development -- \$2,500,000

Equipment:

Snowplow Grader -- \$350,000

Snow Wing Grader -- \$350,000

Grader 34,000# -- \$350,000

Dozer Crawler 8-10T -- \$350,000

Comments:

Surveying airport lease lots, placing fill material, installing fencing and developing an updated land occupancy drawing.

UMNAK - Ft. Glenn

Runway(s): Inactive / Abandoned

Surface:

Lighting:

NAVAIDS:

Classification:

Enplanements:

Borough: Aleutians West

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: ,

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

Extend existing MIRL, update ALP, and acquire additional Right of Way

UMNAK - North Shore

Runway(s): Inactive / Abandoned

Surface:

Lighting:

NAVAIDS:

Classification:

Enplanements:

Borough: Aleutians West

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$-

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement:

Airfield Manager: ,

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

Airport requires fence/gate repair, lease lot development, security fencing, and improved seaplane facilities.

UNALASKA / DUTCH HARBOR (DUT)

Runway(s): 12/30 - 4100' x 100' **Surface:** Asphalt/Grooved **Lighting:** BCN/Rwy_Lts/VASI/REIL
NAVAIDS: NDB/DME

Classification: Regional	# Enplanements: 30,048	Borough: Aleutians West
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$46,008.72
USPS Hub: Yes	School Facility: Yes	Ops Cost/Yr: \$765,958.48
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2012

Airfield Manager: DALE RUCKMAN, 907-581-1786

NEEDS:

Surfaces:

- Rehabilitate pavement (runway, hanger apron, taxiway A, taxiway B, and terminal apron)
- Runway repair (M&O DM)
- Rehabilitate the runway

Dimensional:

- Provide additional RSA off the ends of runway 30-12
- Lengthen the existng runway to meet critical aircraft requirements

Facilities:

- Convert WWII hanger into a chemical storage building
- Rehabilitate the existing WWII hanger into a deicing chemical storage tanks, a mixing tank and a vehicle and miscellaneous M&O storage area
- Remodel existing hanger building to convert into chemical storage building
- Demolish WWII torpedo building. Project includes hazardous material site clean up
- Expand terminal building and ARFF building to accommodate sand

Equipment:

- Deicer truck, dump truck, ARFF vehicle, snow blower, tractor
- Mower, minivan, grader, rescue boat, snowblower

Comments:

VALDEZ (L93) - Robe Lake

Runway(s): E/W, N/S

Surface: Water

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue:

USPS Hub: No

School Facility: Yes

Ops Cost/Yr:

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: STEVE SEARLES, 907-835-5658

NEEDS:

Surfaces:

Valdez Robe Lake SPB Improvements -- \$1,000,000

Dimensional:

Facilities:

Equipment:

Snowplow 1 Way Ridg -- \$350,000

Snow Wing Truck -- \$350,000

ARFF Vehicle -- \$1,000,000

Broom Runway Push -- \$350,000

Truck Plow Airport 4x4 -- \$350,000

Utility Wagon Mid 4x4 -- \$350,000

Handicap Pass Loader -- \$350,000

Comments:

Lease lot development, apron expansion, access ramp (launch) improvements and access road improvements.

VALDEZ (VDZ) - Valdez Pioneer Field

Runway(s): 06/24 - 6500' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/App_Lts/HIRL/REIL/PAPI
NAVAIDS: LDA/DME/NDB

Classification:	Regional	# Enplanements:	16,147	Borough:	Valdez-Cordova
Air Carrier Hub:	No	Medical Facility:	Yes	Annual Revenue:	\$94,562.09
USPS Hub:	No	School Facility:	Yes	Ops Cost/Yr:	\$980,440.45
Part 139 Cert:	Yes	On/Off Road:	Off	Last Major Improvement:	2007

Airfield Manager: STEVE SEARLES, 907-835-4695

NEEDS:

Surfaces:

Dimensional:

Facilities:

Valdez Airport Security Upgrades -- \$2,500,000

Equipment:

Comments:

Construct a deicing material storage building at the Valdez Airport.

WALES (IWK)

Runway(s): 18/36 - 3990' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL/PAPI

NAVAIDS: N/A

Classification: Community

Enplanements: 1,414

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$550.00

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$79,331.85

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1991

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

Wales Airport improvements -- \$5,500,000

Dimensional:

Facilities:

Wales SRE Building Replacement -- \$2,000,000

Equipment:

Dozer Crwlr 8-10T -- \$350,000

Comments:

Resurface runway, apron and taxiway, and install new lighting.

WHALE PASS SPB (96Z)

Runway(s): NW/SE - 10000' x 1000' **Surface:** Water **Lighting:** N/A
NAVAIDS: N/A

Classification: Community	# Enplanements:	Borough: Prince of Wales
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$-
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$-
Part 139 Cert: No	On/Off Road: Off	Last Major Improvement:

Airfield Manager: PAUL KHERA, 907-465-1786

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

WHITE MOUNTAIN (WMO)

Runway(s): 15/33 - 3000' x 60'

Surface: Gravel

Lighting: BCN/Rwy_Lts

NAVAIDS: N/A

Classification: Community

Enplanements: 1,551

Borough: Nome

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$73,726.99

Part 139 Cert: No

On/Off Road: Off

Last Major Improvement: 1991

Airfield Manager: ROBERT MADDEN, 907-443-2500

NEEDS:

Surfaces:

White Mountain Airport Improvements -- \$3,500,000

Dimensional:

Facilities:

White Mountain SRE Upgrade -- \$150,000

Equipment:

Grader 35,000# -- \$350,000

Dozer Crawler 8-10T -- \$350,000

Comments:

Resurface runway, apron and taxiway, apply a dust palliative and upgrade lighting system.

WHITTIER (IEM)

Runway(s): 04/22 - 1480' x 60'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Community

Enplanements:

Borough: Valdez-Cordova

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$-

USPS Hub:

School Facility: Yes

Ops Cost/Yr: \$12,260.04

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: TOM GRMAN, 907-783-2232

NEEDS:

Surfaces:

Dimensional:

Facilities:

Equipment:

Comments:

WILLOW (UO)

Runway(s): 13/31 - 4400' x 75'

Surface: Gravel

Lighting: BCN/Rwy_Lts/REIL

NAVAIDS: N/A

Classification: Local

Enplanements: 1,201

Borough: Matanuska-Susitna

Air Carrier Hub: No

Medical Facility: Yes

Annual Revenue: \$68,436.71

USPS Hub: No

School Facility: Yes

Ops Cost/Yr: \$73,697.04

Part 139 Cert: No

On/Off Road: On

Last Major Improvement: 1989

Airfield Manager: PATRICK D. VARNEY, 907-495-6286

NEEDS:

Surfaces:

- Runway and taxiway resurface
- Construct a new GA apron with 100 tie downs
- Construct vehicle parking for the apron
- Construct new lighted segmented circle

Dimensional:

Facilities:

- Construct a new SREB

Equipment:

- 4 to 6 CY LOADER WHEEL
- SNOW BLOWER

Comments:

- Obstruction removal
- Rehabilitate access road

WISEMAN (WSM)

Runway(s): 02/20 - 2000' x 30'

Surface: Gravel

Lighting: N/A

NAVAIDS: N/A

Classification: Local

Enplanements:

Borough: Yukon-Koyukuk

Air Carrier Hub: No

Medical Facility: No

Annual Revenue: \$-

USPS Hub: No

School Facility: No

Ops Cost/Yr: \$692.76

Part 139 Cert: No

On/Off Road: On

Last Major Improvement:

Airfield Manager: JEFF RUSSELL, 907-451-2207

NEEDS:

Surfaces:

Wiseman Airport Rehabilitation -- \$400,000

Dimensional:

Facilities:

Wiseman Airport Access Road Improvements -- \$200,000

Equipment:

Comments:

Runway surface repairs, brushing, and tree clearing.

WRANGELL (WRG)

Runway(s): 10/28 - 5999' x 150' **Surface:** Asphalt/Grooved **Lighting:** BCN/HIRL/VASI/REIL
NAVAIDS: LDA/DME

Classification: Regional	# Enplanements: 11,674	Borough: Wrangell
Air Carrier Hub: No	Medical Facility: Yes	Annual Revenue: \$38,838.38
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$412,004.15
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2006

Airfield Manager: WILLIE BLOOM, 907-874-3107

NEEDS:

Surfaces:

FY'15 Apron/TWY Rehab -- \$3,000,000

Dimensional:

FY'17 Apron & Lease Lot Development -- \$3,500,000

Facilities:

Equipment:

FY'16 ARFF Truck -- \$1,000,000

FY'18 Self-Propelled Runway Broom -- \$550,000

Comments:

YAKUTAT (YAK)

Runway(s): 11/29 - 7745' x 150'
02/20 - 6475' x 150' **Surface:** Asphalt **Lighting:** BCN/App_Lts/VASI/REIL/PAPI
NAVAIDS: ILS/DME/VOR

Classification: Regional	# Enplanements: 10,517	Borough: Yakutat
Air Carrier Hub: Yes	Medical Facility: Yes	Annual Revenue: \$85,222.75
USPS Hub: No	School Facility: Yes	Ops Cost/Yr: \$574,617.56
Part 139 Cert: Yes	On/Off Road: Off	Last Major Improvement: 2004

Airfield Manager: ROBERT LEKANOF, 907-784-3293

NEEDS:

Surfaces:

FY'15 RWY 11/29 Rehab -- \$7,500,000

Dimensional:

Facilities:

FY'14 Aeronautical Survey -- \$250,000

FY'15 Perimeter Fence -- \$2,000,000

Equipment:

Comments: